

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ / S / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s 365 AUTOMOTIVE

of

Insured: SLU 786M

Policy No. GA588321

Claims No. S2M046OQ

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$105k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMF4959Y Yr Regn: 14 Nov/2018

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1.8S c.c 1797

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 323420

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZVW506144369

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ S/D A/Rim or

Tyre Size: F: 195/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KAPSEN

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/7/2022

D.O.I. 14-07-2022

Survey held at W/S 4:30PM

Des. of Damages: Frt / Rear / O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$9000 - \$10000
	GIA give later
15/7/22	Submit PRS, repair range \$9,000-\$10,000
14/7/23	Submit LS \$8850 (Red 3600, 28%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 11

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) 14/7/23-typist

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Other:

TOTAL

Report Filed:

Long Copy/MP: