

ASS. REC. BY: P. J. M.

REF: CS3/LPC22004438/Rvy3

633D


LOG # 124: 2023/MAY

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMW 4581M
at Workshop m/s: GARAGE 13
of _____
Insured: GBF 3444C LPC
Policy No. _____
Claims No. 21/22/22/VC05/025722
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 19K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 4581M Yr Regn: 2013 / MAY
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Golf A71.4 C.C. 1395
Colour: GREY A/C: Insured / Std / NI / NA
Sp. Reading: 78878 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVWZZZ4H2DW099234
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modl: NII / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/40R18
R: _____
BS / DUN / EXNOVA / SV / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 26/04/22 D.O.I. 27/04/22
Survey held at GARAGE 13
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 9K
12/5/22	ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 12/5/22-typist

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

Report Format: _____

Lump Sum / L.B.K. (\$) _____

Volkswagen Golf 1.4A TSI

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$20,800****Depreciation**

\$15,950 /yr

[View models with similar depre](#)**Reg Date**

13-Jun-2013

(1yr 1mth 8days COE left)

Mileage

165,000 km (18.5k /yr)

Manufactured

2013

Road Tax

\$624 /yr

Transmission

Auto

Dereg Value

\$10,911 as of today (change)

OMV

\$20,925

COE

\$67,301

ARF

\$6,295

Engine Cap

1,395 cc

Power

90.0 kW (120 bhp)

Curb Weight

1,249 kg

No. of Owners

2

Type of Vehicle[Hatchback](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	033D
Vehicle No.:	SMW4581M
Vehicle to be Exported:	No
Intended Deregistration Date:	04 May 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT BMT 5G13GZ
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CMB125122
Chassis No.:	WVWZZZAUZDW099234
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,925.00
Original Registration Date:	27 May 2013
First Registration Date:	27 May 2013
Transfer Count:	1
Actual ARF Paid:	\$6,295.00
PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2023
PARF Rebate Amount:	\$3,462.00
COE Rebate Details	
COE Expiry Date:	26 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$61,029.00
COE Rebate Amount:	\$6,463.00
Total Rebate Amount:	\$9,925.00

The information contained herein is correct as at 04 May 2022

OK