

ASS. REC. BY:

REF:

AWA CS/AWA22009936/Kny3

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/10

Check body sticker insured or not ??

Policy does covered sticker up to \$1,000.00

Finalized amount confirmed @ \$3200 b/gst. Repair day 4 days.

(red, \$2523.33, 44%)

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

1) 05/05/23

☐

: Final Report

Date/Time, File Return to?

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Transportation

\$ - R.S. \$

: Frt

: Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

7/10/2022



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : ODIns Company : ALLIED WORLDExcess : Date of Accident : 23.09.2022Suggested Days of Repair : **Repair Estimates**Parts (a) Cost / List Price Items \$ 3,366.66Plus/Less 10% \$ 336.67Total of Cost / List \$ 3,703.33(b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,703.33Labour (Appendix B) \$ 2,020.00Total Repair Cost \$ 5,723.33

The above total will be subjected to 7% G.S.T.

Vehicle No. : GBC1061CMake & Model : FIAT / DOBLO CARGO 1.3MJYear of Manufacture : 2011Chassis No. : ZFA269300009097831Engine No. : 199A30004067319Policy No. : Time of Accident : 1255**In-house Vehicle Assessor**Case Owner : Johari BHSignature : **Contact No****Frt Counter Operation**

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com

**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

NOT Authorized  
 1/Rep &  
 Summary After Pain  
 Ex \$1500

Name of Surveyor : Kenneth  
 Company : UKIC  
 Survey conducted on : 10/10/22 at

**Remarks By Surveyor**(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor : Le Date: 10/10/22



**Spare Parts**

Vehicle No : GBC1061C Case Owner : Johari BH  
 Make & Model : FIAT / DOBLO CARGO 1.3M. Year Manufacture : \_\_\_\_\_  
 Chassis No : ZFA269300009097831 Engine No : 199A30004067319  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : OD

| S/No | Part Description                   | QTY | Cost Price | List Price | Nett Price | S/N | Disposit Surveyo |
|------|------------------------------------|-----|------------|------------|------------|-----|------------------|
| 1    | BONNET <i>Bu</i>                   | 1   | \$ 683.42  |            |            |     | ✓                |
| 2    | WICK, BUMPER, FR                   | 1   | \$ 69.30   |            |            |     | ✓                |
| 3    | HEADLAMP RH <i>my Bu</i>           | 1   | \$ 419.45  |            |            |     | ✓                |
| 4    | FRONT FENDER RH <i>Bu</i>          | 1   | \$ 265.14  |            |            |     | ✓                |
| 5    | HEADLAMP LOWER BEAM RH             | 1   | \$ 75.60   |            |            |     | X                |
| 6    | RADIATOR GRILLE <i>Pu</i>          | 1   | \$ 76.20   |            |            |     | ✓                |
| 7    | BUMPER SIDE BRACKET RH <i>Di-7</i> | 1   | \$ 25.23   |            |            |     | X                |
| 8    | BUMPER SIDE BRACKET LH <i>Pu</i>   | 1   | \$ 25.23   |            |            |     | ✓                |
| 9    | CROSSRAIL, BUMPER FR               | 1   | \$ 357.19  |            |            |     | ✓                |
| 10   | BONNET HINGE RH                    | 1   | \$ 69.50   |            |            |     | ✓                |
| 11   | BONNET HINGE LH                    | 1   | \$ 68.18   |            |            |     | ✓                |
| 12   | CLAMPING KIT BUMPER FR <i>me</i>   | 1   | \$ 34.62   |            |            |     | ✓                |
| 13   | BUMPER TOP GRILLE <i>Pu</i>        | 1   | \$ 323.29  |            |            |     | X                |
| 14   | BUMPER FRT <i>Bu/CM</i>            | 1   | \$ 756.25  |            |            |     | ✓                |
| 15   | ORNAMENT,GRILLE <i>ms</i>          | 1   | \$ 118.06  |            |            |     | ✓                |
| 16   |                                    |     |            |            |            |     |                  |
| 17   |                                    |     |            |            |            |     |                  |
| 18   |                                    |     |            |            |            |     |                  |
| 19   |                                    |     |            |            |            |     |                  |
| 20   |                                    |     |            |            |            |     |                  |
| 21   |                                    |     |            |            |            |     |                  |
| 22   |                                    |     |            |            |            |     |                  |
| 23   |                                    |     |            |            |            |     |                  |
| 24   |                                    |     |            |            |            |     |                  |
| 25   |                                    |     |            |            |            |     |                  |
| 26   |                                    |     |            |            |            |     |                  |
| 27   |                                    |     |            |            |            |     |                  |
| 28   |                                    |     |            |            |            |     |                  |
| 29   |                                    |     |            |            |            |     |                  |
| 30   |                                    |     |            |            |            |     |                  |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Tel: 63837168 / 63837466 Fax: 62815767**

## 2011

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                                       |
|---------------------------------|---------------------------------------|
| Date of Submission              | 23/09/2022 19:08 (SGT)                |
| Reported by                     | Driver                                |
| Time of Accident                | 23/09/2022 12:55 (SGT)                |
| Exact Location of Accident      | Near 915 Whampoa Dr, Singapore 327780 |
| Additional Location Information | CTE AFTER JALAN BAHAGIA EXIT          |
| Country/State of Loss           | Singapore                             |

## DETAILS OF OWN VEHICLE

|                             |                        |
|-----------------------------|------------------------|
| Vehicle Registration Number | GBC1061C               |
| INSURED/POLICYHOLDER        |                        |
| Is company?                 | Yes                    |
| Name Of Registered Owner    | F&N FOODS PTE LTD      |
| Company Reg No              | 1XXXXX390K             |
| Email Address               | yanli.sim@fnnfoods.com |
| Mobile Phone No             | (Phone) +65-62108261   |
| Alternative Phone No        | -                      |

## VEHICLE PARTICULARS

|                                                                              |                     |
|------------------------------------------------------------------------------|---------------------|
| Manufacturer                                                                 | Fiat                |
| Model                                                                        | Doblo               |
| Variant                                                                      | CARGO 1.3MJ         |
| Exact purpose for which vehicle was being used at time of accident           | Employment          |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Reporting only |
| Vehicle Category                                                             | Commercial vehicle  |
| Transmission                                                                 | Auto                |
| CC                                                                           | 1248                |

## INSURANCE COMPANY

|                                   |                                     |
|-----------------------------------|-------------------------------------|
| Name of Insurance Company         | Allied World Assurance Company, Ltd |
| Policy Number / Cover Note Number | BVFCB0013692102                     |


## DRIVER

|                |              |
|----------------|--------------|
| Name of Driver | HEW FOO RONG |
| Work Permit No | GXXXX225K    |
| Date Of Birth  | 21/03/1990   |
| Occupation     | Indoor       |

SKETCH PLAN

Jalan Bahagia

CTE After Jalan Bahagia



CTE

- A SNE8928D
- B GX8685L
- C GBC106K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23-04-2022 around 12.55pm, I was traveling at CTE after Jalan Bahagia Exit. Suddenly Infront of Van (VEH B) (Silver color) crash to ~~VEH A~~ a Car (VEH A) (white color). I ~~try~~ to ~~take~~ am try to emergency brake with my van (vehicle C) (Blue color) but end up my vehicle slightly crash to the van (Vehicle B)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

F & N FOODS PTE LTD

214 Pandan Loop

Singapore 128405

Policyholder's Signature No. 62108108

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

23/4/22

2.55pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# Require PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

390K

## Vehicle Details

Vehicle No.:

GBC1061C

Vehicle to be Exported:

No

Intended Deregistration Date:

05 Oct 2022

Vehicle Make:

FIAT

Vehicle Model:

DOBLO CARGO 1.3MJ

Primary Colour:

White

Manufacturing Year:

2011

Engine No.:

199A30004067319

Chassis No.:

ZFA26300009097831

Maximum Power Output:

\$18,576.00

Open Market Value:

25 May 2011

Original Registration Date:

25 May 2011

First Registration Date:

0

Transfer Count:

\$929.00

Actual ARF Paid:

## Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

\$0.00

PARF Rebate Amount:

## Intended COE Rebate Details

COE Expiry Date:

30 Apr 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

QP Paid:

\$19,991.00

COE Rebate Amount:

\$14,271.00

Total Rebate Amount:

\$14,271.00

## Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

Information contained herein is correct as at 05 Oct 2022

OK