

7/10/2022

1st



ComfortDelGro Engineering
205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : OD

Vehicle No. : GBC1061C

Make & Model : FIAT / DOBLO CARGO 1.3MJ

Year of Manufacture : 2011

Chassis No. : ZFA269300009097831

Engine No. : 199A30004067319

Policy No. : _____

Time of Accident : 1255

Ins Company : ALLIED WORLD

Excess : _____

Date of Accident : 23.09.2022

Suggested Days of Repair : _____

In-house Vehicle Assessor : _____

Case Owner : Johari BH

Signature : _____

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,366.66

Plus/Less 10% \$ 336.67

Total of Cost / List \$ 3,703.33

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 3,703.33

Labour (Appendix B) \$ 2,020.00

Total Repair Cost \$ 5,723.33

Contact No

Frt Counter Operation
63837103 - Patrick Tia
PatrickTia@sparkcarcare.com
63837730 - Brenda Ng
BrendaNg@sparkcarcare.com
63837466 - Rohani
RohaniM@sparkcarcare.com

Workshop Operation
63837656 - Ngo Toh Wee
Ntohw@sparkcarcare.com
63838115 -
63837362 -

LS\$3200

*Not Authorized
1/1 Ring & 2 Hood
Painting After Paint
Ex \$1500*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Henneth
Company : UKIC
Survey conducted on : 10/10/22 at _____

Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Sc Date: 10/10/22

