



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22009956/Avy3e2

Date: 13/12/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNG 5433Z	Veh. Inspected	SKS 4150T
Policy No.	P10793284R00	Coverage (\$)	0.00
Claim No.	C10017935/JL	Excess (\$)	0.00
Assign From	SALIZAWATI HAIZAR	Assign Date	10/10/2022

2. Vehicle Particulars & Condition

Make & Model	CITROEN PICASSO	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF73A9HC8EJ804124	Colour	BRONZE
Odometer	310310 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	ROTALLA	6 mm
L/H Front Tyre	215/55 R17	ROTALLA	6 mm
R/H Rear Tyre	215/55 R17	ROTALLA	6 mm
L/H Rear Tyre	215/55 R17	ROTALLA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/10/2022	Inspection Date	10/10/2022
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**