

ASS RECD BY:

REF:

AISI

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

3100/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

889k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

09130

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 48974 Regn: 12, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i

c.c

2497

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

123347

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP 32070C 547508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/45R18

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

8/10/22

D.O.I.

11/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Wksp said part by part, unable to locate 2nd parts

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS. SI


Paints

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002752224-01	Date of Loss:	08/10/2022
Vehicle Reg. No.:	SMU4897M	Driveable?	
Driver Age/Info:	23 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ALVIN TAN YANG HAI	Contact No:	+6596750429
Driver:	JAMIE TAN (CHEN SHENGWEI)		

Make/Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	28/12/2010
Vehicle Colour:	BLACK		
Engine No:	06017631N52B25AF	Chassis No:	WBAFP32070C547508
Odometer:	1 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) *18 7 days*

*Not Withheld
Penalty B & C
Ex @ 31000*

Description of Accident/Loss: REFER TO SAS.

Remarks: VEHICLE IS IN.

Present Location: FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	18,617.60
Labour	0.00
Paintwork Labour	2,720.00
Towing	0.00
	0.00
Gross Total (S\$)	21,337.60
+ GST 7.00% (S\$)	1,493.63
Nett Amount (S\$)	22,831.23

This claim is handled by: ANDY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)

Parts: 143 BMW 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SMU4897M/11/10/2022 13:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Bonnet	0.00	0.00	Ry *2,400.00 F	✓
2	1		*LH Bonnet Hinge	0.00	0.00	R *100.00 F	X
3	1		*RH Bonnet Hinge	0.00	0.00	R *100.00 F	X
4	1		*LH Bonnet Lock	0.00	0.00	Dit *210.00 F	✓
5	1		*RH Bonnet Lock	0.00	0.00	R *210.00 F	X
6	1		*Bonnet Insulator Clip	0	0.00	*60.00 FS	?
7	1		*Bonnet Latch (Pull Handle)	0.00	0.00	nd *20.00 F	✓
8	1		*Air Duct	0.00	0.00	CM *290.00 F	2
9	1		*Radiator Support Bar	0.00	0.00	*185.00 F	?
10	1		*Radiator Support	0.00	0.00	*280.00 F	?
11	1		*LH Stay Bar	0.00	0.00	*50.00 F	?
12	1		*RH Stay Bar	0.00	0.00	*50.00 F	?
13	1		*LH Headlamp	0.00	0.00	*2,700.00 F	?
14	1		*RH Headlamp	Bo 0.00	0.00	*2,700.00 F	✓
15	1		*LH Headlamp Panel	0.00	0.00	*250.00 F	?
16	1		*RH Headlamp Panel	0.00	0.00	R *250.00 F	X
17	1		*Front Bumper	CM 0.00	0.00	*1,300.00 F	✓
18	1		*Front Bumper Logo	nd 0.00	0.00	*85.00 F	✓
19	1		*Front Bumper Reinforcement	0.00	0.00	Ry *750.00 F	✓
20	1		*Front Bumper Sponge	0.00	0.00	CM *125.00 F	✓
21	1		*Front Bumper Lower Grille	0.00	0.00	Dit *115.00 F	✓
22	1		*Front Bumper Tow Cover	0.00	0.00	*55.00 F	?
23	1		*Front Bumper Lower Beam	0.00	0.00	*170.00 F	?
24	1		*LH Headlamp Washer	0.00	0.00	*200.00 F	?
25	1		*RH Headlamp Washer	0.00	0.00	*200.00 F	?
26	1		*LH Headlamp Washer Cover	0.00	0.00	sn *55.00 F	X
27	1		*RH Headlamp Washer Cover	0.00	0.00	nti *55.00 F	✓
28	1		*LH Headlamp Washer Cover Bracket	0.00	0.00	*18.00 F	?
29	1		*RH Headlamp Washer Cover Bracket	0.00	0.00	*18.00 F	?
30	2		*Front Bumper Fog Garnish	0.00	0.00	*200.00 F	?
31	1		*Front Bumper Sensor - RH	0.00	0.00	nti *190.00 F	✓
32	1		*Front Bumper Sensor - RH Center	0.00	0.00	nti *190.00 F	✓
33	1		*Front Bumper Sensor - LH Center	0.00	0.00	nti *190.00 F	✓
34	1		*Front Bumper Sensor Wire	0.00	0.00	*210.00 F	?
35	1		*LH Front Grille	0.00	0.00	Bo *165.00 F	✓
36	1		*RH Front Grille	0.00	0.00	CM *165.00 F	✓
37	1		*LH Front Fender Inner Garnish	0.00	0.00	sn *265.00 F	X
38	1		*RH Front Fender Inner Garnish	0.00	0.00	sn *265.00 F	X
39	1		*RH Fog Lamp	0.00	0.00	nti Bo *285.00 F	✓

Qty	Part No.	Particulars	%Disc	%Depr	Amount	
40	1	*Air Con Condenser	0.00	0.00	*850.00 F	?
41	1	*Radiator	0.00	0.00	*820.00 F	?
42	1	*LH Radiator Top Holder	0.00	0.00	*15.00 F	?
43	1	*RH Radiator Top Holder	0.00	0.00	*15.00 F	?
44	1	*Front Number Plate	0	0.00	*55.00 FS	—
45	1	*Front Bumper Clip	0	0.00	*60.00 FS	—

F=Franchise part. S=SpcNett.

Sub Total (S\$)	16,941.00
+ Margin on L,N Items 10.00% (S\$)	1,676.60
Total Parts (S\$)	18,617.60

Falcon-Air Auto Services Pte Ltd/SMU4897M/11/10/2022 13:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Labour Items</u>			
1	To check wiring and focus headlamp	New	200 50.00
2	To vacuum, re-oil and re-gas air con	New	100 120.00
3	To computer reset electronic functions	New	250.00
4	To remove/replace radiator support panel, repair inner panel, front chassis, LH/RH front fender including replacement of parts	New	700 1,100.00
5	To spray paint bonnet, bumper, front inner panel, LH/RH front fender	New	800 1,200.00
Gross Labour Cost (S\$)			2,720.00

Falcon-Air Auto Services Pte Ltd/SMU4897M/11/10/2022 13:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	563C
Vehicle Details	
Vehicle No.:	SMU4897M
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2022
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	06017631N52B25AF
Chassis No.:	WBAFP32070C547508
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$43,917.00
Original Registration Date:	28 Dec 2010
First Registration Date:	28 Dec 2010
Transfer Count:	3
Actual ARF Paid:	\$43,917.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2030
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$34,935.00
COE Rebate Amount:	\$27,841.00
Total Rebate Amount:	\$27,841.00

The information contained herein is correct as at 11 Oct 2022

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/10/2022 16:10 (SGT)
Reported by	Driver
Date of Accident	08/10/2022 13:00 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMU4897M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ALVIN TAN YANG HAI
NRIC No	SXXXX563C
Email Address	alsterenator@gmail.com
Mobile Phone No	(Phone) +65-96750429
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2497

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2002752224-01

DRIVER

Name of Driver	JAMIE TAN (CHEN SHENGWEI)
NRIC No	SXXXX245A
Date Of Birth	21/07/1999
Occupation	Indoor



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

CTC



SJS 8210 P

SMU 4897 M



F. V. M. Loh