

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |  |                 |            |                     |  |
|---|---|--|-----------------|------------|---------------------|--|
|   | STRIDES AUTOM   | OTIVE SERVICES PTE LTD                               | Re              | ef:        | CS/SMR22010024/Tny3 |  |
|   | 60 WOODLANDS I<br>E4SINGAPORE 75  | Da   | ate:            | 11/10/2022 |                     |  |
|   |   |  | Co              | ode:       | SMR                 |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |  |                 |            |                     |  |
|   | Insured Veh.  | SHB 1100H  | Veh. Inspected  |            | SNA 9222X           |  |
|   | Policy No.  |  | Coverage (\$)   |            | 0.00                |  |
|   | Claim No.   | TAX/10/22/2011                                       | Excess (\$)     |            | 0.00                |  |
|   | Assign From   | HUA YEN  | Assign Date     |            | 11/10/2022          |  |
| 2. Vehicle Particulars & Condition                                |   |  |                 |            |                     |  |
|   | Make & Model  |  | c.c             |            | 0                   |  |
|   | Engine No.  | HIDDEN   | Year of Reg.    |            |                     |  |
|   | Chassis No.   |  | Colour          |            |                     |  |
|   | Odometer  | -  | Steering        |            |                     |  |
|   | Brakes  |  | Modification    |            |                     |  |
|   | General   |  |                 |            |                     |  |
| 3. Conditions of Tyres  |   |  |                 |            |                     |  |
|   |   | Size   | Make            |            | Balance             |  |
|   | R/H Front Tyre  |  |                 |            | mm                  |  |
|   | L/H Front Tyre  |  |                 |            | mm                  |  |
|   | R/H Rear Tyre   |  |                 |            | mm                  |  |
|   | L/H Rear Tyre   |  |                 |            | mm                  |  |
| 4.  | Description of Damages  |  |                 |            |                     |  |
|   |   |  |                 |            |                     |  |
| 5.  | 5. General Information  |  |                 |            |                     |  |
|   | Accident Date   | 05/10/2022   | Inspection Date |            | 12/10/2022          |  |
|   | Survey held at  | DICKSON AUTO CARE CENTRE PTE LTD                     |                 |            |                     |  |
|   |   | 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619 |                 |            |                     |  |
| 5a. Remarks   |   |  |                 |            |                     |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |            |                     |  |