

ASS. REC. BY:

REF:

LPC / 22010030/K

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

11-11-30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 865k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5-6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 6996B Yr Regn: 061 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) WagonMake: Toy Estima C.C. 2362Colour: h. Black A/C: Insured / Std / NI / NASp. Reading: 52796 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR 50 0190232

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 235/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FalkenFront: 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 29/9/22 D.O.I. 17/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / Tail pole jammed

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authorized
 61 kg @
 Missing After Repair
 Ex 8600
 5-6 days



The Motor Claims Department
 M/s Lompac Insurance Bhd
 300 Beach Road, #17-04/07
 The Concourse
 Singapore 199555

File No :
 Date :

07-October-2022

Estimated cost of repair for vehicle no : SKA6996B Toyota Estima
 Policy no: Z22VP05031418
 Accident Date: 29.09.2022

Description	Quantity	Cost Price
	1	\$ 680.00 ✓
Tailgate	1	\$ 40.00 ✓
Tailgate emblem	1	\$ 40.00 ✓
Tailgate badge "estima"	1	\$ 40.00 ✓
Tailgate badge "aeras"	1	\$ 190.00 ?
Tailgate inner lock	1	\$ 150.00 ?
Tailgate weatherstrip	1	\$ 350.00 ?
Tailgate inner trim board	1	\$ 75.00 ✓
Rear windscreen moulding	1	\$ 280.00 ✓
Rear bumper	1	\$ 15.00 ✓
Rear bumper clips (1 set)	1	\$ 20.00 ✓
Rear bumper tow cover	1	\$ 40.00 X
RH Rear bumper reflector	1	\$ 40.00 ✓
LH Rear bumper reflector	1	\$ 55.00 ?
RH Rear bumper sponge	1	\$ 55.00 ?
LH Rear bumper sponge	1	\$ 45.00 ✓
RH Rear bumper retainer	1	\$ 45.00 ✓
LH Rear bumper retainer	1	\$ 40.00 ?
RH Rear bumper bracket	1	\$ 40.00 ?
LH Rear bumper bracket	1	\$ 280.00 ?
Rear end panel	1	\$ 180.00 ?
Rear end panel top trim	1	\$ 450.00 ?
Rear floor panel	1	\$ 250.00 ?
Rear floor panel top trim board	1	\$ 3,400.00
		Add 15% \$ 510.00
		\$ 3,910.00
Rear bumper parking sensors (1 set)	1	S. nett \$ 280.00 2005m
Rear windscreen sealant	1	S. nett \$ 60.00 805m
Rear windscreen inner seal	1	S. nett \$ 28.00 ✓

To remove and reinstall rear windscreen and conduct water leak test	\$	120.00	✓
To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace damaged parts and adjust rear body and tailgate alignment	\$	650.00	600
To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	\$	800.00	750
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality	\$	50.00	20
To perform computer diagnostic on parking system, ABS systems, and clear fault codes	\$	150.00	7
To apply anti-corrosion Tuff-Kote	\$	80.00	NZ X
	\$	<u>6,128.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/09/2022 11:52 (SGT)
Reported by	Both
Date of Accident	29/09/2022 07:15 (SGT)
Exact Location of Accident	Hougang Ave 4, Singapore
Additional Location Information	Hougang Ave 4 towards Florene Road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA6996B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Ng Kian Yap
NRIC No	SXXXX205F
Email Address	mike@legionnetgp.com
Mobile Phone No	(Phone) +65-91116996
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Estima
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2400

INSURANCE COMPANY

Name of Insurance Company	Lonpac Insurance Bhd
Policy Number / Cover Note Number	Z22VP05031418

DRIVER

Name of Driver	Ng Kian Yap
NRIC No	SXXXX205F
Date Of Birth	19/09/1969
Occupation	Indoor

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by The General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes, mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



A - SKA 6980B

B - SGY 66991

C - QUS 57196

Back to OneMotoring

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

Vehicle No.:

205F

Vehicle to be Exported:

SKA6996B

Intended Deregistration Date:

Yes

Vehicle Make:

29 Sep 2022

Vehicle Model:

TOYOTA

Primary Colour:

ESTIMA AERAS 2.4 A

Manufacturing Year:

Black

Engine No.:

2015

Chassis No.:

2AZJ147595

Maximum Power Output:

ACR500190232

Open Market Value:

125.0 kW (167 bhp)

Original Registration Date:

\$29,018.00

First Registration Date:

19 Jun 2015

Transfer Count:

19 Jun 2015

Actual ARF Paid:

0

Intended PARF Rebate Details

\$32,626.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

18 Jun 2025

PARF Rebate Amount:

\$19,575.00

Intended COE Rebate Details

COE Expiry Date:

18 Jun 2025

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

COE Paid:

\$78,001.00

COE Rebate Amount:

\$21,232.00

Net COE Rebate Amount:

\$40,807.00

Information contained herein is correct as at 29 Sep 2022

OK