

Income (Wsum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.10.2022

Time: 10:29:54

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305532345
REGN NO : SHB6220L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 05.01.2017
DATE/TIME IN : 10.10.2022 09:30
ACCIDENT DATE : 07.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	X / CRA
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	X nn
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	? x nn
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	? x nn
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ MC

SUB-TOTAL : 1,080.72

JOB NATURE

0000	PB	PANEL BEATING	300.00	280
0001	SP	SPRAYPAINT CHARGE	300.00	250

SUB-TOTAL : 600.00

TOTAL : 1,680.72

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged panel during resurvey
- Parts prices are based on market rate
- Third party claims are processed on "Prejudice" basis
- No other services are provided
- Supplies are not guaranteed to be covered and is subject to the terms and conditions of the Company

A

(Handwritten signature)
 28/10/22
 Y/S
 Guna Ong
 10/10
 3pm