

Income (Wsum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.10.2022

Time: 10:29:54

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305532345  
REGN NO : SHB6220L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 05.01.2017  
DATE/TIME IN : 10.10.2022 09:30  
ACCIDENT DATE : 07.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	<del>X</del> / CRA
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	X m
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ m

SUB-TOTAL : 1,080.72

JOB NATURE

0000	PB	PANEL BEATING	300.00	280
0001	SP	SPRAYPAINT CHARGE	300.00	250

SUB-TOTAL : 600.00

TOTAL : 1,680.72

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

*Handwritten notes:*  
2 days  
4/5  
Gone by  
10/10  
3pm

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged panel during resurvey
  - Parts prices are based on market rate
  - Third party's liability is on "Prejudice" basis
  - No other charges are included
  - Surveys are conducted on a "no fee" basis and is not to be charged to the Company