

Our Job Ref No : 305532348  
Date : 13.10.2022

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHC2618U

Date of Accident : 08.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- SNB9383J
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges (include advertisement stickers etc,if any)
  - Total for Part-By-Part Repair Cost**
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$700.00  
**Final Lumpsum Repair cost** \$700.00
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Signature : \_\_\_\_\_

Name : LIM T S

Name : GUO QIANG

Tel : 62148398

Date : \_\_\_\_\_

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_