

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Income (Usun)

Date: 10.10.2022

Time: 09:55:51

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305532341
 REGN NO : SHD4558R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 01.03.2019
 DATE/TIME IN : 10.10.2022 09:00
 ACCIDENT DATE : 08.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0595-G	PANEL ASSY-REAR DOOR RH#	1	2,147.90	20.00	1,718.32	X Kpi
0002 04-01-0104-2466-G	W/STRIP ASSY-FR DR BELT	1	125.30	20.00	100.24	X nn
0003 28-01-9999-2032-A	ZIG BOOK NOW APP LOGO REA	1 N	80.00	10.00	72.00	/ Kc

SUB-TOTAL : 1,890.56

JOB NATURE

0000 PB	PANEL BEATING	800.00	350
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 L	TRANSFER DOOR PARTS	120.00	X NN

SUB-TOTAL : 1,520.00

TOTAL : 3,410.56

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts price and substitution confirmation
- Third party liability on "Without Prejudice" basis
- No illegal modification allowed
- Supplemental damage must be resurveyed and is subject to approval by Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 Day
 9/5
 10/10
 Gmnd
 2 pm