

ASS RECDY. *T. G. J. M.*

REF: *CS/LIP22010056/Twy3*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *9242K*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *Thana*

Vehicle: IN / OUT

Veh No: *SM729145* Yr Regn: *2021 / Apr 1*

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Mercedes Benz* E200 C.C. *1991*

Colour: *Grey* A/C: Insured / Std / NI / NA

Sp. Reading: *16576* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WIK213080214891124*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *245/45R18*

R: *245/45R18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. _____ D.O.I. *12/10/22*

Survey held at *Jade Cars*

Des. of Damages Fr / Rear / O/S / N/S / WC / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass 10?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Loop Sum / I.B.E. /



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 08/10/2022
VEHICLE : SMZ2914J
MAKE & MODEL : MERC E200
INSURANCE : LIBERTY
SURVEYOR : LKK ADRIAN

PARTS		AMOUNT
1.	REAR BUMPER 1800 de ✓	\$ 2100
2.	REAR BUMPER DIFFUSER 365 X m	\$ 450
3.	REAR BUMPER CHROME GARNISH 340 cut ✓	\$ 380
4.	REAR BUMPER REFLECTOR - LEFT 142 cut ✓	\$ 210
5.	REAR BRAKE LIGHT - LEFT cut ✓	\$ 3200
6.	REAR FENDER - LEFT Rpx	REPAIR
	5482 10% - 4933.80	
	SPECIAL NETT	
1.	CLIPS , SCREWS & RIVETS 50 new ✓	\$ 100
2.	PARKING SENSOR (2 PCS) 1m's ✓	\$ 390
	440	
	LABOUR	
1.	TO PUTTY & SPRAY PAINT ON AFFECTED AREA 500	\$ 700



JACK CARS

DRIVE WITH ASSURANCE

2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		\$ 1000 500
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	✓	50? \$ 250
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	no	X \$ 220
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY		60 \$ 280
6.	TO REMOVE & REINSTALL SENSORS		40. \$ 200
		1150	
	PARTS - 10%:		\$ 5,706
	SPECIAL NETT :		\$ 490
	LABOUR :		\$ 2,650
	TOTAL :		\$ 8,846
	7% GST :		\$ 619.22
	GRAND TOTAL :		\$ 9,465.22

Taufik 97495749

wp' 12/10/22 @ 430

p/p Resury before paint

taufik @ lkhauto.com

- to check consistency of accident.
- to check part prices

3-4 days

before paint before 13/10/22.

4933.80

440

1150

46523.80

3 days

*