

ASS. REC. BY:

REF:

SPF / 22010065/kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3-6 days

Res.: Yes or No

Lum Sum:

1-B11 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Pmn 28875

Yr Regn: 05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo XC60 T5 c.c. 1969

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

81943

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

YV10Z40LDG2845647

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal.

8

mm

Rear

R/Bal.

5

mm

L/Bal.

8

mm

L/Bal.

5

mm

D.O.A.

2/10/22

D.O.I.

14/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$)



: Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

SPF ACCIDENT CLAIM SECTION
LOGISTICS SUPPORT & SERVICES DIVISION
POLICE LOGISTICS DEPARTMENT, POLICE LOGISTICS BASE
1 HEMMANT ROAD, Singapore 099253
Attn: Motor Claim Department

Not Asbestos
Recovery B4 point
5-6 days

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SMN2887S
MODEL : VOLVO XC60
POLICY NO :
CHASSIS NO : YV1DZ40LDG2845647
YEAR OF MANUFACTURE : 2016
DATE / TIME OF ACCIDENT: 02/09/2022 Time: 1055Hrs at PIE CHANGI AROUND TOA PAYOH
THIRD PARTY VEHICLE NO: QX2104T

Date: 13/10/2022
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price S\$	Amount S\$
S/N				
1	REAR BUMPER <i>Buc</i>	1		
2	REAR BUMPER DIFFUSAL <i>Del</i>	1		
3	REAR REINFORCEMENT BAR <i>?</i>	1		
4	REAR BRAKE LIGHT LH <i>mx</i>	1		
5	REAR BRAKE LIGHT RH <i>mx</i>	1		
6	REAR BUMPER RETAINERS <i>mx</i>	2		
7	REVERSE SENSORS <i>?</i>	4		
8	REAR FENDER RH <i>mx</i>	1		
9	REAR FENDER LH <i>mx</i>	1		
10	TAILGATE <i>cas</i>	1		
11	BOOT TRUCK <i>mx</i>	1		
12	TAILGATE WEATHER STRIP <i>mx</i>	1		
13	Volvo EMBLEM REAR <i>acc</i>	1		
14	REAR END PANEL <i>?</i>	1		
15	TOW COVER <i>mx</i>	1		
16	XC60 EMBLEM <i>acc</i>	1		
17	REAR WINDSCREEN <i>mx</i>	1		
18	T5 EMBLEM <i>acc</i>	1		
19	REAR END PANEL GANISH <i>mx</i>	1		
20	REAR CHROME BUMPER GANISH <i>mx</i>	1		
21	REAR WINDSCREEN MOULDING <i>mx</i>	1		
22	REAR BUMPER SPONGE <i>?</i>	1		
23	TAILGATE BOARD <i>?</i>	1		
24	TAILGATE LOCK <i>?</i>	1		
25	TAIL GATE SUSPENSION RH <i>mx</i>	1		
26	TAILGATE SUSPENSION LH <i>mx</i>	1		
27	TAILGATE HINGE RH <i>mx</i>	1		
28	TAILGATE HINGE LH <i>mx</i>	1		
29	EXHUAUST CHROME GANISH RH <i>!</i>	1		

Kenneth

30	EXHUAUST CHROME GANISH LH	7	1
31	TAILGATE LOCK ECU	Snx	1

Sub-Total: -
Less: 10% discount -
Total Parts after 10% discount: -

Special Nett Items

1	Anti-rust coating	2	80.00	160.00	7
2	Number plate	1	80.00	80.00	X
3	Number plate Holder	1	50.00	50.00	X
4	Rear End panel Sealant	1	100.00	100.00	?
5	Rear Bumper Clips	20	2.90	58.00	✓
6	REAR WINDSCREEN SEALANT	1	100.00	100.00	40sm
7	REVERSE CAMERA	1	350.00	350.00	X

898.00

Total Parts: 898.00

Labour Charges For Front

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	500- 700	2,400.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	750	2,400.00
3	Provide skill labour to disconnect and check electrical wiring	20	150.00
4	Remove and replace bumper sensors	60	150.00
5	Remove and replace of rear windscreen	120	300.00
6	Dismantle and Transfer rear boot fitting and mechanism to new boot/facilitate repair	60	150.00
7	Remove and refit rear end panel ling and garnish to facilitate repair	7	150.00
8	Reset Engine management system and diagnostic fault	7	350.00
9	Provide skill labour to remove and replace reverse camera to facilitate repair	50	200.00

Total Labour:

Total Parts & Labour:
GST 7%
Grand Total:

6,250.00
7,148.00
500.36
7,648.36

Estimate Repair Duration

15 days

ACCIDENT VEHICLE OF : SMN2887S

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: Ninja Lo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/09/2022 17:29 (SGT)
Reported by	Driver
Date of Accident	02/09/2022 10:55 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	Towards Changi (near Toa Payoh)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN2887S
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHO EUN JOO
Passport No/FIN	G5037157W
Email Address	decohousing@naver.com
Mobile Phone No	(Phone) +65-85180467
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Volvo
Model	Xc60
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1969

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1900231161-02

DRIVER

Name of Driver	Park Song Hee
Passport No/FIN	G5036920Q
Date Of Birth	17/08/1967
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

05 SEP 2022

SOH JIT HOON

Sketch Plan

Handwritten sketch plan on a grid background:

- Top left: A → SMN 28875
- Bottom left: B → QX 21047
- Top right: PIG
- Center: A diagram showing two rectangular boxes connected by a horizontal line, with arrows pointing outwards from the boxes.