C2/Ea/1/2	1006/1/40/3
	GMMENT
From: Date:	Veh No: SM K. 99357 Yr Regn: 29/19/10
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OO / P WS / TP RES / OD RES / EVA / INV / MV	Truck / Traller or
To Inspect Vehicle No:	Make: VOIKSWAGEN TOULON c.c 1395
at Morkshop m/s	Colour Wite A/C: Insured / Std / NI / NA
ol	Sp.Reading 30839 T/Radio: Insured / Std / NI / NA
insured:	Eng/No:
Palicy No.	CNO: WV6722112KW072656.
Claims No.	Gen. Cond: God / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: In order / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ingraer / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil /SIRIm (STD A/Rim of
·	Tyre Size: F: 215/50R16
(Policy Condition)	. R:
Remark: The veh had commenced its . N/S O/S	BS I DUN / EXNOVA I GY / FS I LIZA MIC OHTSU I PIR I SUMI
repair at the time of inspection.	TOYO I YOKO or .
Bail. or Market Value:	Front Rear
iDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	UBal. 5 mm UBal. 5 mm
Est Repairs: 12 days Res.: Yes or No	D.O.A. 4 10/1/
Lum Sum: % · 3 Val.: Yes or No	Survey held at Yo KS Wag or
CA / REV / REP. / 24 HRS	Des. of Damages: Frt Rear O/S N/S U/C Rooftop or
Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to callision.
Date:Person Contacted:	The O/C / Chassis frame / Body offocial characters
Date / Time Action / Instruction	
Steve finalised final fig \$19458.9	5, 12 days. (Red \$9990.24, 34%)
	<u> </u>
Osle/Time, File Pass to? : Preli. Report	Days Of Repair: 12
₁ 01/12 Typist : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add F	ee! : Sife Insp (\$) _s + Rssi
	: Interview (\$) Proks
Repart Formet: MER-TP	: Tech, Invs (\$); Others
19458.95)	Medicuel (S
13400.30)	TOTAL

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road

Singapore 159934 Biz. Reg. No.: 199101494Z GST No.: M200985052

Steve (LKK) 12 Js 13/10/22, 9:30 p/p

1/3

05-10-2022





Non binding - Preview

Company ERGO INSURANCE PTE. LTD 5 TEMASEK BOULEVARD

#04-01 SUNTEC TOWER FIVE Singapore 038985

Customer Details: Ms. NUR RAISAH RASID MRS NUR RAISAH LACAVE 237 UPPER PAYA LEBAR ROAD #01-46 Singapore 533867

Page Document no. Document date Customer no. Customer GST-ID Dealer

Quotation

5211001034 199305211H 30001 2022029206/1 Job order number 04-10-2022 Job order date YEN MEI WONG Service Advisor

License plate SMV9935Z

Model code 5T13NZC0

First registration 29-10-2020

VIN WVGZZZ1TZKW072656 Model Touran Comfortline 1.4 I TSI 110kW DSG Mileage 30,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax	code	1000	al amount excl. GST	Total amou
		-00	A STATE OF	A TOTAL TO SERVICE AND ADDRESS.	and the same of the same of	#1	THE REAL PROPERTY.	280.00/	299.
9801B004	B&P CHECK SHORT CIRCUIT / HARNE					#1		480.00	
9801B005	B&P DIAGNOSIS AND PROGRAMMING	3				#1		102.88	/ 110.
D 169300M2	1k Window Adhesive	2	pcs.	51.44				102.88	100
0 00940104	All Purpose Cleaner	1	pcs.	102.88		#1		30.27	
00920002	Primer	1	pcs.	30.27		#1		26.27	. 33
181802M1	Activator	1	pcs.	26.27		#1		22.32	
0 00950025	Applicator	2	pcs.	11.16		#1		2.788.77/	
TA827025Q	Rear Trunk Lid	1	pcs.	2,788.77	01.47	#1			
5TA827939 041	Spoiler Satin Black	1	pcs.	304.32	c Photo)	#1	nec	304.32	323.
1A02/939 041	REAR W/SCREEN SIDE TRIM LH				•			200 07 /	331.
5TA827940 041	Spoiler Satin Black	1	pcs.	309.67		#1	CUT	309.67/	331.
51A827940 041	REAR W/SCREEN SIDE TRIM RH								
D0052440D	Packing Adhesive	1	pcs.	32.91		#1	nec	32.91/	35.
8D0853419D	RR NUMBER PLATE PACKING		•				200		/
	Rivetted Cap Nut	4	pcs.	2.64		#1	nec	10.56	11.
WHT007341	Hood Latch	1	pcs.	192.96		#1		192.96	? 206.
5TA827505D	BOOT LID LOCK								1
	Vw Sign Black/Bright Chro	1	pcs.	117.06		#1	Nec	117.06	/ 125.
5TA853630A DPJ	Inscription Bright Chrome	1	pcs.	80.37		#1	nec	80.37	86.
5TA853687 2ZZ	NAME PLATE - TOURAN				.1.0				
	Additional Brake Light Wi	1	pcs.	245.82	(phot)	#1	MC	245.82/	263.
3CN945087					4		20		
	3RD BRALELIGHT	1	pcs.	287.30		#1	ak	287.30	307.
5TA945094E	Taillight With Back-Up Li RHS TAILLIGHT INNER	•					-		,
		1	pcs.	344.61		#1	AR	344.61	368.7
5TA945096D	Tail Light		poo.				4		
	RHS TAILLIGHT OUTER	2	pcs.	0.49		#1	rec	0.98 /	
5TA945229	Mounting	1	pcs.	11.62		#1	nec	11.62	12.4
5TA945300	Attachment Element		poo.						
	BOLT	1	pcs.	132.95		#1		132.95 X	142.2
5TA827550M	Gas-Filled Strut		poo.						
	RHS BOOT LID ABSORBER	2	pcs.	5.17		#1	Nec.	10.34	
1K8827951	Plug	1	pcs.	17.40		#1	Nec		
8X0827499	Buffer Adjustable	- 1	pcs.	346.72		#1		346.72 X	370.9
5TA827705A	Gasket BOOT LID WETHERSTRIP	•	P 00.						
	Cover For Bumper Primed	1	pcs.	1,537,14		#1	00	1,537.14	
5TA807417 GRU		i	pcs.	368.79		#1		368.79	! 394.6
5TA807568A 9B9	Spoiler Satin Black	i	pcs.	682.38		#1		682.38	730.1
5TA807305	Bumper REINFORCEMENT		P00.				44.	Anna Marie A	
11 0405007	Bolt Hex. Hd. With Should	7	pcs.	4.44	1	#1	nec	31.08	33.2
N 0195307	The state of the s	1	pcs.	72.88		#1		72.88	77.9
5TA807863	Attachment Strip BUMPER CTR BRACKET		poo.	. 2.00					0
FT4.007.450	The state of the s	1	pcs.	49.88		#1	,	49.88	53.3
5TA807453	Guide Piece	,	pos.	10.00			1	2.00	

LKSWAGEN CENTRE SINGAPORE

7 Alexandra Road Singapore 159934 Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Page

2/3

Company ERGO INSURANCE PTE. LTD 5 TEMASEK BOULEVARD

#04-01 SUNTEC TOWER FIVE Singapore 038985 Customer Details: Ms.

NUR RAISAH RASID

MRS NUR RAISAH LACAVE 237 UPPER PAYA LEBAR ROAD

#01-46

Singapore 533867

Document no.
Document date
Customer no.

Customer no. Customer GST-ID Dealer Job order number 5211001034 199305211H 30001 2022029206/1

05-10-2022

Job order date

Job order date

Service Advisor

Job order number

04-10-2022

YEN MEI WONG

License plate SMV9935Z Model code 5T13NZC0 First registration 29-10-2020 VIN WVGZZZ1TZKW072656 Model
Touran Comfortline 1.4 I TSI 110kW DSG

Mileage 30,315

				1		1	
Position no.	Description	Quantity	y Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5TA807454	Guide Piece (/hoh)	1	pcs.	49.88	#1	BR 49.88	53.37
3 1A007434	RHR BUMPER BRACKET (UPPER)						c
5TA807393	Guide Piece	1	pcs.	40.61	#1	40.61	43.45
	LHR BUMPER BRACKET (SIDE)					RP 40.61	/ 43.45
5TA807394	Guide Piece) 1	pcs.	40.61	#1	BR 40.61	43.40
	Guide Piece RHR BUMPER BRACKET (SIDE)	1	200	75.79	#1	75.79	7 81.10
5TA945104	Reflector RHS REFLECTOR OUTER	1	pcs.	13.13			1
ETAD4E406	Reflector	1	pcs.	75.79	#1	75.79	81.10
5TA945106	RHS REFLECTOR INNER	•	poo.				
5TA845042ACNVB	Side Window Not Pre-Treat	1	pcs.	441.08	#1	Nec 441.08	471.96
7170400427101118	RHR FENDER GLASS					41	,
169300M2	1k Window Adhesive	1	pcs.	51.44	#1	OFC 51.44	,
0 00920002	Primer	1	pcs.	30.27	#1	nec 30.27	
181802M1	Activator	1	pcs.	26.27	#1	MC 26.27	
00950025	Applicator	2	pcs.	11.16	#1		
TA809844	Sectional Part Side Panel RHR FENDER	1	pcs.	2,155.11	#1	00 2,155.11/	
506KD1A4	2k-Insert Foam	1	pcs.	163.23	#1	AC 163.23	
476KD1M2	Sealant Can Be Sprayed	1	pcs.	66.78	#1	NC 66.78	
007500A2	Zinc Spray	1	pcs.	72.86	#1	n' (72.86/	
180003M2	2k-Body Adhesive	1	pcs.	469.52	#1	AC 469.52	
VWLM6114	UNDERSEAL	1	pcs.	15.50	#1	NC 15.50	
5TA810972A	Wheelhouse Protector RHR FENDER LINER	1	pcs.	229.65	#1	229.03	1
5TA809857B GRU	Fuel Filler Door With Hou	1	pcs.	225.19	#1	223.19	240.5
5TA010000A	Tire Pressure Label	1	pcs.	15.15	#1	15.15	16.2
5TA821714D	Stone Protection Foil RHR FENDER FOIL	1	pcs.	35.98	#1	P(35.98	
6R0819465C	Vent Trim RHR FENDER AIR DUCT	1	pcs.	42.93	#1	42.93	45.94
6N0809966A	Expanding Nut	5 _	pcs.	2.42	#1	N(12.10 /	12.95
	LABOUR	85	pcs.	840.00	4200 #1	6,720.00	7,190.40
	SPRAY PAINT	8 7	pcs.	800.00	2490 #1	4,800.00	. 5,136.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00/	898.80
	R&R RHS REAR FENDER GLASS	1	pcs.	840.00	470 #1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	420 #1	840.00	898.80
	R&R REAR SEAT UTO ([] AT)	, 1	pcs.	840.00	#1	840.00	898.80
	R&R REAR LUGGAGE TRIM 477 (Ph	/ 1	pcs.	840.00	#1	840.00	98.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	RHR FENDER GLASS SOLAR FILM AVIVA VS ERGO	1	pcs.	200.00	#1	200.00	214.00
	3RD PARTY VEHICLE GBM9991M						
	D.O.A: 04-10-2022 SURVEY BY:						
	SURVEY DT.						

LKSWAGEN CENTRE SINGAPORE

7 Alexandra Road Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052







Quotation

Non binding - Preview

Page

3/3

Company ERGO INSURANCE PTE. LTD 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE Singapore 038985

Customer Details: Ms. NUR RAISAH RASID MRS NUR RAISAH LACAVE 237 UPPER PAYA LEBAR ROAD

#01-46 Singapore 533867 Document no. Document date Customer no. Customer GST-ID Dealer Job order number

Job order date

Service Advisor

199305211H 30001 2022029206/1 04-10-2022 YEN MEI WONG

05-10-2022

5211001034

License plate SMV9935Z

Model code 5T13NZC0

First registration 29-10-2020

VIN WVGZZZ1TZKW072656 Model

Touran Comfortline 1.4 I TSI 110kW DSG

Mileage 30,315


Quotation valid till 11-10-2022

Tax	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
Code #1	760.00	28,689.19	7%	2,061.44	29,449.19	31,510.63
Total	760.00	28,689.19		2,061.44	29,449.19	31,510.63
					VOLKSWA GROUN SINGAPO	'

Customer	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and	SINGAPORE 8 150 Advisor
VISIT OUR WEBSITE:	is subject to final approval from Insurance Company aftersales www.com.su (for opline, service appointments) and volkswage Signature: Date:	en.com.sg and www.skoda.com.sg (for additional services, products

All invoices are denominated in SGD, unless otherwise stated.

2A40002 / Ajax Mars Pte Ltd Y DATE & TIME: 04/10/2022 14:13 (SGT) MITTED BY: Victor RSION: 1 (04/10/2022 14:13 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Prease report correctly the details of the economic to speed up the Calmis process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

The issue and acceptance of this Form by insurance companies is not an admission panel.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Country/State of Loss

Additional Location Information

04/10/2022 14:13 (SGT)

Driver

04/10/2022 08:35 (SGT)

Singapore

Temasek club entrance

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMV9935Z

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No

NUR RAISAH RASID MRS NUR RAISAH LACAVE

SXXXX615B

Geoffrey.lacave@gmail.com

(Phone) +65-87985408

VEHICLE PARTICULARS

Manufacturer

Model

Variant Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

Volkswagen

TOURAN 1.4 TSI CL 5T13NZ HLG

Private use

No - Claiming third party

Private car

Auto

1400

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Singapore Life Ltd

11097961

DRIVER

Name of Driver NRIC No Date Of Birth

Occupation

LACAVE GEOFFREY SXXXX009B

12/04/1991 Indoor

Accident report SA1D22A40002

Page 1 of 32



20/04/2016 6 YEARS AND 6 MONTHS **Date Of Driving Pass** Driving experience Male Gender (Phone) +65-91718017 Mobile Number Alt. Phone Number Geoffrey.lacave@gmail.com **Email Address** Foresque Residences, 105 Petir Road Address #07-10 Address complement 678274 Postcode No Is the driver the policyholder? Spouse If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

Co Medician Number
Vehicle Versen
Vehicle Colour
Name of Divisory

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	
Was anybody injured in the Accident?	2 No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	
Translator's phone number	
Translator's email	
Original language used in the statement	-

PASSENGER 1

Name	P1
Gender	Male
PASSENGER 2	
Name	P2
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-


CIRCUMSTANCES OF ACCIDENT

Arriving at Temasek club main entrance, I had to break as a car in front was moving, the van hit my car at the read right side after I break, i managed to take some photos and exchange particulars with the 3rd party party and I also had an in car camera footage of the scene. No injuries was involved at the scene.

Male

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes



DETAILS OF OTHER VEHICLE PROPERTY 1

Asta Danistantian Number	GBM9991M
chicle Registration Number	Nissan
Vehicle Manufacturer	
Vehicle Model	Nv350
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Commercial vehicle
Name of Driver	CHIN JUO WI
NRIC No	SXXXX870J
Contact Number	(Phone) +65-96237686
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Notice Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2



SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

porting Officer Bin Mohd Affand
ting Centre





Policyholder's Signature / Date &	Driver's Signature (if driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
	A second	Witnessed By Reporting Officer Muhammad Sumardi Bin Mohd Affand
We declare the foregoing particula	rs are true in every respect.	
Declaration		
exchange particulars v	ead right side after I break, I managed to vith the 3rd party party and I also had a was involved at the scene.	n in car camera rootago ex
van hit my car at the re	ub main entrance, I had to break as a clead right side after I break, i managed to	take some photos and

