



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                            |                                                                                                                                        |                                                                       |                                                         |            |
|----------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|---------------------------------------------------------|------------|
| ERGO INSURANCE PTE LTD<br>8 TEMASEK BOULEVARD, #04-01 SUNTEC<br>TOWER THREE SINGAPORE 038988 |                                                                                                                                        |                                                                       | Ref: CS/EGI22010067/y3<br>Date: 12/10/2022<br>Code: EGI |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                            |                                                                                                                                        |                                                                       |                                                         |            |
|                                                                                              | Insured Veh.                                                                                                                           | GBM 9991M                                                             | Veh. Inspected                                          | SMV 9935Z  |
|                                                                                              | Policy No.                                                                                                                             |                                                                       | Coverage (\$)                                           | 0.00       |
|                                                                                              | Claim No.                                                                                                                              | CDMCG22002057                                                         | Excess (\$)                                             | 0.00       |
|                                                                                              | Assign From                                                                                                                            | PAULINE SOH                                                           | Assign Date                                             | 12/10/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                |                                                                                                                                        |                                                                       |                                                         |            |
|                                                                                              | Make & Model                                                                                                                           |                                                                       | c.c                                                     | 0          |
|                                                                                              | Engine No.                                                                                                                             | HIDDEN                                                                | Year of Reg.                                            |            |
|                                                                                              | Chassis No.                                                                                                                            |                                                                       | Colour                                                  |            |
|                                                                                              | Odometer                                                                                                                               | -                                                                     | Steering                                                |            |
|                                                                                              | Brakes                                                                                                                                 |                                                                       | Modification                                            |            |
|                                                                                              | General                                                                                                                                |                                                                       |                                                         |            |
| <b>3. Conditions of Tyres</b>                                                                |                                                                                                                                        |                                                                       |                                                         |            |
|                                                                                              |                                                                                                                                        | Size                                                                  | Make                                                    | Balance    |
|                                                                                              | R/H Front Tyre                                                                                                                         |                                                                       |                                                         | mm         |
|                                                                                              | L/H Front Tyre                                                                                                                         |                                                                       |                                                         | mm         |
|                                                                                              | R/H Rear Tyre                                                                                                                          |                                                                       |                                                         | mm         |
|                                                                                              | L/H Rear Tyre                                                                                                                          |                                                                       |                                                         | mm         |
| <b>4. Description of Damages</b>                                                             |                                                                                                                                        |                                                                       |                                                         |            |
|                                                                                              |                                                                                                                                        |                                                                       |                                                         |            |
| <b>5. General Information</b>                                                                |                                                                                                                                        |                                                                       |                                                         |            |
|                                                                                              | Accident Date                                                                                                                          | 04/10/2022                                                            | Inspection Date                                         |            |
|                                                                                              | Survey held at                                                                                                                         | VOLKSWAGEN CENTRE SINGAPORE<br>247 ALEXANDRA ROAD<br>SINGAPORE 159934 |                                                         |            |
| <b>5a. Remarks</b>                                                                           |                                                                                                                                        |                                                                       |                                                         |            |
|                                                                                              | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                       |                                                         |            |