



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|     |   | Affiliated to Federation Internation   | nale Des Experts Er | Automok    | pile                 |
|-----|---|--|---------------------|------------|----------------------|
|     | AXA INSURANCE PTE LTD   |  | Ref:                |            | CS3/ASM22010078/Gvy3 |
|     | 8 SHENTON WAY<br>AXA TOWERSING  | Date:                                  |                     | 12/10/2022 |                      |
|     |   |  |                     | Code:      | ASM                  |
| 1.  | Policy Particulars :- (THIRD PARTY CLAIM)   |  |                     |            |                      |
|     | Insured Veh.  | SHD 4558R                              | Veh. Inspected      | d          | SMF 4899L            |
|     | Policy No.  |  | Coverage (\$)       |            | 0.00                 |
|     | Claim No.   | S2M04CHV                               | Excess (\$)         |            | 0.00                 |
|     | Assign From   | KHOR SAW THENG                         | Assign Date         |            | 12/10/2022           |
| 2.  | Vehicle Particulars & Condition   |  |                     |            |                      |
|     | Make & Model c.c  |  |                     |            | 0                    |
|     | Engine No.  | HIDDEN                                 | Year of Reg.        |            |                      |
|     | Chassis No.   | Colour                                 |                     |            |                      |
|     | Odometer  | Steering                               |                     |            |                      |
|     | Brakes  | Modification                           |                     |            |                      |
|     | General   |  |                     |            | _                    |
| 3.  | Conditions of Tyres   |  |                     |            |                      |
|     |   | Size                                   | Make                |            | Balance              |
|     | R/H Front Tyre  |  |                     |            | mm                   |
|     | L/H Front Tyre  |  |                     |            | mm                   |
|     | R/H Rear Tyre   |  |                     |            | mm                   |
|     | L/H Rear Tyre   |  |                     |            | mm                   |
| 4.  | Description of Damages  |  |                     |            |                      |
| _   |   |  |                     |            |                      |
| 5.  | General Information   |  |                     | 40/40/0000 |                      |
|     | Accident Date   | 08/10/2022                             | Inspection Da       | te         | 12/10/2022           |
|     | Survey held at  | KENT AUTO SERVICES  2 KAKI BUKIT AVE 2 |                     |            |                      |
|     |   |  |                     |            |                      |
| 5a. | Remarks   |  |                     |            |                      |
|     | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |  |                     |            |                      |