

 Service Request Details

Claim	S2M04CHV
Reference	CS3/ASM22010078/Svy3m4 
Loss Date	8 October 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	10 Oct 2022 11:25:19 AM
Request Date	11 October 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SMF4899L
Vehicle	
Registration #	
Make	TPVD - Toyota
Model	Noah

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Other	Other	do not reply	

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SKETCH PLAN.pdf.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2206547.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2022
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2022
 SMF 4899L IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2022
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL, Akash	11 October 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL, Akash	11 October 2022
 INSD GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL, Akash	11 October 2022
 SJ0G22A8000C-SHD4558R.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	10 October 2022