

(L8/11/13) Web

ASS. REC. BY: John

REF:

CS/ASM 22010086/Rqy3

620E

ASSIGNMENT

From:

Date:

Veh No:

SLG 64460

Yr Regn:

2016 / 6C1

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLG 64460

Make:

HONDA CIVIC 1.6 VTI CUT c.c. 1597

at Workshop m/s

FDK Automobile

Colour:

BLACK

A/C: Insured / Std / NI / NA

of

39, WINDMILLS CL #05-12 @ MEGA

Sp. Reading

099142

T/Radio: Insured / Std / NI / NA

Insured:

ASM

Eng/No:

C/No:

MRH FC5650GT000 436

Policy No.

Gen. Cond: Good / Fair / Poor / Burnt

Claims No.

Steering: In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: In order / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / S/Rim / STD A/Rim or

Make of Veh:

Tyre Size: F:

215/50R17

R:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value:

67K

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

3

days

Res.: Yes or No

D.O.A.

28/09/22

D.O.I.

12/10/22

Lum Sum:

%

3 Val.: Yes or No

Survey held at

FDK Automobile

CA / REV / REP. / 24 HRS

Des. of Damages Fr Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 32K

Repair Finalised US \$1000, 3 days (Red \$1200, 55%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

3

1)

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format :

Smart Claims - TP

Lump Sum / I.B.I. (\$

1000

☐

: Weekend (\$

TOTAL



FDK AUTOMOBILE & LEASING SERVICES PTE LTD

UEN/GST NO.: 201611065K
39 WOODLANDS CLOSE MEGA @ WOODLANDS
#05-12 SINGAPORE 737856
OFFICE: 69526590

Fabian Wong: 9191 6590
Daryl Wong: 9772 9698
Kenneth Wong: 97553198

Date: 11th October 2022

ESTIMATE COSTING FOR CAR REPAIR

To: AXA INSURANCE

Car Plate No: SLG6446D

Desription	Qty	Price S\$
1) Front Grille Base <i>del</i>	1x	\$360.00 ✓ <i>360</i>
2) Front Grille Chrome <i>del</i>	1x	\$210.00 X <i>20%</i>
3) Bumper Clips <i>del</i>	1x	\$130.00 X <i>288</i>
4) Bumper Retainers <i>del</i>	2x	\$310.00 X
5) Repair Front Bumper		\$190.00 <i>150</i>
6) Front Bumper, Grille Base, Front Grille, Spray Matt	4x	<i>950</i> } \$360.00 <i>300 + 1w = 4w</i>
7) Labour For Dismantal , Installation , Adjustment & Electrical Dismantal	4x	<i>950</i> } \$460.00 <i>300 + 1w = 4w</i>

Total Amount Excluding GST \$2,020.00

7% GST \$141.40

Total Amount Including GST \$2,161.40



Authorised By

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resm
4p 90010068

3 days

4/5

12/10/22 @ 1220

Resy after repair

Accepted By:

4/5 \$1000 / 3 days

288
950
1238
20%
990.40