

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

05510

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1. Respon Expiry 13-03-2032

During survey front door already repair back

only door checker replaced 1 item only so p/p repair

27/5/23

p/p \$1500.85 insured Elin

Veh No:

PC 1312M

Yr Regn:

14/03/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota hiace Hirof.c.c 2982

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

188790

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFST22P900012869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

06/10/22

D.O.I.

12/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S p/f.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

AUTOWERKS

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17 October 2022

NOT Authorised
see

17/10/22

P/p # 1506.85

4 days

REG NO.: PC 1312 M
MAKE/MODEL: TOYOTA HIACE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front door -RH	\$ 1,670.00 X
1	Front door checker	\$ 35.80
1	Front door glass outer moulding	\$ 133.95 X
2	Front door hinges	\$ 155.96 X
1	Front door inner board	\$ 897.50 X
1	Front door lock	\$ 272.50 X
1	Front door regulator	\$ 211.36 X
1	Front door regulator motor	\$ 489.55 X
1	Front door rubber	\$ 190.05 X
1	Front door run channel	\$ 156.60 X
1	Front door side mirror	\$ 450.60 X
1	Front door outer pillar -RH	\$ 711.50 X
1	Front headlamp -RH	\$ 1,700.20 X
1	Front corner panel -RH	\$ 376.50 X
		\$ 7,452.07
	Less 25%	\$ 1,863.02
		\$ 5,589.05

SPECIAL NETT ITEMS

1	Front door company sticker	\$ 280.00
		\$ 280.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$ 200.00 50
3	To apply undercoating.	\$ 200.00 30
4	Panel beating.	\$ 800 - 550
5	To re-spray painting on the affected areas.	\$ 1,500.00 - 550
		\$ 1,996.00

1200

GRAND TOTAL :

\$ 7,865.05

P-35.8
252
26.85
280
1200

L60685

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
~~PC1312M~~

Make / Model
TOYOTA / TOYOTA HIACE HIROOF AUTO 14 SEATER

Vehicle Type :
P20 - Passenger Bus/Coach/Minibus

Vehicle Scheme :
Voluntary Welfare Organisation (VWO)

Propellant :
Diesel

Motor No. :
-

Power Rating :
-

Maximum Laden Weight :
3200 kg

Year Of Manufacture :
2011

Lifespan Expiry Date :
13 Mar 2032

Road Tax Expiry Date :
13 Mar 2023

Inspection Due Date :
13 Mar 2023

CO2 Emission :
-

CO Emission :
-

NOx Emission :
-

Vehicle Attachment 1 :
Air-Conditioned

Chassis No. :
JTF5T22P900012869

Engine No. :
1KD2153510

Engine Capacity :
2982 cc

Maximum Power Output :
-

Unladen Weight :
2280 kg

Original Registration Date :
14 Mar 2012

COE Category :
-

PARF Eligibility Expiry Date :
-

Intended Transfer Date :
12 Oct 2022

CEV/VES Rebate Utilised Amount :
-

HC Emission :
-

PM Emission :
-

Fees To Be Paid For Transfer

Transfer Fees

\$25.00

Print

OK ➔