

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: _____

at Workshop m/s COMFORT LOYANG

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC3372X Yr Regn: 21 Apr/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi Prime Mover /

Truck / Trailer or _____

Make: HYUNDAI I40 c.c. 1685

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41UMGU087798*

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12-10-2022

Survey held at W/S 3PM

Des. of Damages: Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Filed at _____

Long Quid / MPB /

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : W/Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Other: _____

TOTAL