

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305532428
Date : 13.10.2022

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHA 351L

Date of Accident : 11.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- SILVERCAB
SHD1410C
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (include advertisement stickers etc,if any) _____
 - Total for Part-By-Part Repair Cost** _____
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$750.00
Final Lumpsum Repair cost \$750.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : _____
Name : GUO QIANG
Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:
