

Our .	Job Ref No 🕃		305532441			diverking	
Date : 19.10.2022					ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	LIZATION FO	ORM					
To	LKK				Fax:		
Attn	GUO QIANG						
Vehic	de Reg No.	: SHA	9799U		11.10.2022		
The	survey and es	timates of	the repairs of the above-	mentioned vehicle	e are as follows	31-	
z	The repair job shall bill to:			INCOME	INCOME SKV2501L		
2.	The finalize	d amount :	shall be:				
	(a) Spare	e Parts aft	er List discount				
	(b) Labo	ur Charge	3				
	Total	for Part-I	By-Part Repair Cost				
	(c.) Lump	sum Rena	uir (if applicable)				
	Total	for Lumps	um repair cost after Less	pair cost after Less:		\$4.550.00	
	rinai	Lumpsur	n Repair cost			\$1,550.00	
4.5.	7 working days			W	nd Confirmed if there is no reply from you within We confirm the estimates and finalized amount		
	Signature :	/		Signature:			
		CHIANG		 -	Name :		
	Tel : 62148314			Da	Date :		
	Fax :	6546815	6				
For O	fficial Use O	nly					
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Re	Rental Rate P/Day			YES			
2. Lo	2. Loss of Income Paid		#9	N			
	3. Survey Fees		======================================	12			
LTA Search Fee Medical Fees (on behalf of driver, if applicable) Overrun		\$7.49/\$2.00	YES				
Rema		•					