

Our Job Ref No : 305532442 Date 5 17/10/22

ComfortDelGro Engineering Pte Ltd

Date . 17710/22						59 Loyang Drive Singapore 508969 Fax: 6546 8156					
FINA	LIZAT	ION FORM									
То	: ,		LKK			Fax:					
Attn	: M	r	Guo Qiang								
Vehic	cle Reg	No. SHD	4184K				11.10.2022				
The	survey	and estimates of	the repairs of the abov	e-mentioned	d vehicl	e are as follow	vs:-				
1.	The repair job shall bill to:			INCOME		- 100 0	SML455D				
2.	The f	inalized amount	shall be:								
	(a)	Spare Parts aft									
	(b)	Labour Charge	-								
	Total for Part-By-Part Repair Cost						\$0.00				
	(c.)	Total for Lumps	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less;				\$2,300.00				
		Final Lumpsur	n Repair cost				\$2,300.00				
 4. 5. 	7 woo	rking days k you for your as: uture: Ms. Loke	sistance.	ct and Conf	We confirm the estimates and finalized amount Signature: Name Date						
	Tel	: 6214835									
	Fax : 65468156										
For C	fficial	Use Only									
		Item	Amount	Atta	ument iched or No	Confirm By (Signature)	Remarks				
Rental Rate P/Day				Y	ES						
2. Loss of Income Paid					10						
3. Survey Fees											
4. LTA Search Fee			\$7.49 / \$2.00								
Medical Fees (on behalf of driver, if applicable) Overrun											
O Overruit					_						

Remark	s:			