

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 (OD / TP / WS / TP RES / OD RES / EVA / INV / MV)  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: XE5826R Yr Regn: 18/9/20  
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or \_\_\_\_\_  
 Make: Mitsubishi Fuso FV70 c.c. 10677  
 Colour: Green A/C: Insured / Std / Nil / NA  
 Sp. Reading N/A T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: FV70HJSA10001  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jaimmed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: Nil / S/Rim / STD / R/Rim or \_\_\_\_\_  
 Tyre Size: F: 295/80R 22.5  
 R: ??

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Sailun  
 Front Rear  
 R/Bal. 4 mm R/Bal. 0 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 7/10/12 D.O.I. 12/10/12  
 Survey held at Goldbell  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>MV-177K</u> <u>waiting estimate</u>

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time, File Return to?  
 1) \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Lump Sum / L.B.F. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$I \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	753C
Vehicle Details	
Vehicle No.:	XE5826R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Oct 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FV70HJD2VDEA
Primary Colour:	White
Secondary Colour:	Green
Manufacturing Year:	2020
Engine No.:	470912C0518410
Chassis No.:	FV70HJA10001
Maximum Power Output:	-
Open Market Value:	\$117,084.00
Original Registration Date:	18 Aug 2020
First Registration Date:	18 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$5,855.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Aug 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$24,100.00
COE Rebate Amount:	\$18,923.00
<b>Total Rebate Amount:</b>	<b>\$18,923.00</b>

The information contained herein is correct as at 10 Oct 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	11/10/2022 10:25 (SGT)
Reported by	Driver
Date of Accident	07/10/2022 15:03 (SGT)
Exact Location of Accident	Tanah Merah Coast Rd, Singapore
Additional Location Information	BETWEEN LAMP POST 234 & 236
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE5826R
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	LBL CONSTRUCTION PTE. LTD.
Company Reg No	2XXXXX753C
Email Address	lblcontracts@gmail.com
Mobile Phone No	(Phone) +65-96470913
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Fuso
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	10677

### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00099622200

### DRIVER

Name of Driver	KARUPPIAH ARIYAKKANNAN
Passport No/FIN	GXXXX824K
Date Of Birth	04/03/1982
Occupation	Outdoor

Date Of Driving Pass	29/11/2019
Driving experience	2 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96470913
Alt. Phone Number	-
Email Address	lblcontracts@gmail.com
Address	5037 ANG MO KIO INDUSTRIAL PARK 2 #01-391
Address complement	-
Postcode	569540
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Fire, explosion or lightning
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No




**Describe Circumstances of the Accident**

In 7/10/2022 at about 8:03pm, I was driving along Tana Meroh (east Road) on the way to unload the sand when suddenly I see smoke and fire coming out from my vehicle.

I \_\_\_\_\_ (Owner/Driver), Identification No. \_\_\_\_\_, Vehicle No. \_\_\_\_\_  
will be sending the above stated damaged vehicle to \_\_\_\_\_ (Company Name) for my  
vehicle repair works and insurance claims. Goldbell Engineering Pte Ltd "GBE" had clearly informed me on new GIA rules and  
I accept all liabilities and discharged GBE.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
\_\_\_\_\_  
Policyholder's Signature / Date &  
Time



  
\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date  
& Time



\_\_\_\_\_  
Witnessed by Reporting Centre  
Personnel



IMAGES #7





Motor Commercial

MZ301C  
N SN  
AN0679A  
Gov Type C

**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1969  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No	DMCVSNW00099622200	Engine No	47091202618410
		Cha No	FV704JA10001
1. Index Mark and Registration Number of Vehicle	XE 5826R	AUTOSAFE	
2. Name of Policy Holder	LBL CONSTRUCTION PTE LTD		
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	18/08/2022 (00.00.00)	Excess Sect1	\$53,000.00
		EX ON WINDSCREEN	\$5100.00
4. Date of Expiry of Insurance	17/08/2023		
5. Persons or Classes of Persons entitled to drive*			
(1) Whilst the vehicle is being used in connection with the Policyholder's business Any person provided he is in the Policyholder's employ and is driving on their order or with their permission			
(2) Whilst the vehicle is being used for social, domestic or pleasure purposes Any person who is driving on the Policyholder's order or with their permission Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle			
6. Limitations as to use*			
(1) Use in connection with the Policyholder's business			
(2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business			
(3) Use for social, domestic or pleasure purposes			
The Policy does not cover			
(1) Use for racing, pace-making, reliability trial or speed testing			
(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle			
(3) Use for the carriage of passengers for hire or reward			
HIRE PURCHASE CO. UNITED OVERSEAS BANK LIMITED			
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia) are not to be included under these headings			

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By ABWIN PTE LTD  
Authorised Officer

Authorised Signatory