

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMA 131L Yr Regn: 2019/19
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mitsubishi Eclipse c.c. 1499
 Colour: white A/C: Insured / Std / Nil / NA
 Sp. Reading 8400 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: JMAX GK 1W K2 000617
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R18
 R: "

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/> N/S	<input checked="" type="checkbox"/> O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 17/10/22 D.O.I. 17/10/22
 Survey held at with Hang
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-117K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Repair Format: _____
 Lump Sum / L.S. (%) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:

Transportation:	_____ \$ + RS. _____ \$
Photos	_____
Others	_____
TOTAL	_____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	654A
Vehicle Details	
Vehicle No.:	SMQ131L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	ECLIPSE CROSS 1.5 CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	4B40GG9079
Chassis No.:	JMAXTGK1WKZ000617
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$24,726.00
Original Registration Date:	20 Sep 2019
First Registration Date:	20 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$26,617.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2029
PARF Rebate Amount:	\$19,962.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,602.00
COE Rebate Amount:	\$26,774.00
Total Rebate Amount:	\$46,736.00

The information contained herein is correct as at 12 Oct 2022

OK



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Page No. 1

Vehicle No. **SMQ131L MITSUBISHI ECLIPSE CROSS 1.5**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear door LH / <i>OD</i>		650.00	
1	Rear door lower garnish LH / <i>CVT</i>		130.00	
1	Rear door lower side garnish LH / <i>CVT</i>		90.00	
1	Rear fender wheel arch garnish LH / <i>M/S</i>		120.00	
1	Petrol tank door <i>X</i>		195.00	
1	Rear bumper <i>X R</i>		500.00	
1	Rear bumper side retainer LH <i>!</i>		23.00	
1	Rear bumper lower garnish / <i>CVT</i>		130.00	
1	Rear fender LH (Repair refer to labour) <i>X R</i>		0.00	
			1838.00	
			15%	
			275.70	
			2113.70	
			30	
			35.00	
			800.00	
<u>SPECIAL NETT ITEMS</u>				
1	Rear bumper clips / <i>MC</i>			
1	Rear rim 18 inch / <i>CVT</i>			
SN Items Total:			835.00	
Total Parts			2948.70	



Wah Hong Motors & Credit Pte Ltd
 Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
 Email: motor@wahhong.sg
 (199806235M)

Vehicle No. SMQ131L MITSUBISHI ECLIPSE CROSS 1.5

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	/
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To remove and refit/replace rear door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	50
5	To remove and refix rear tyre LH and wheel balancing in order to replace rear rim LH	50.00	30
6	To check and adjust wheel computerize alignment	80.00	/
		Labour Total :	1710.00
		TOTAL (PARTS & LABOUR):	4658.70

Store (CLKK)
 17/10/22, 19.30p
 WZK

00 ~~the~~ P/P (no used parts)
 MM AL my AL y
 EXAM - ? S d r

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: