

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
 at Workshop m/s COMFORT LOYANG

of _____
 Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD4027G Yr Regn: 30 Oct/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi Prime Mover /

Truck / Trailer or

Make: HYUNDAI AE IONIQ HEV 1.6 c.c 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVLU187729 *

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 12-10-2022

Survey held at W/S 3PM

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Naz finalised LS \$1950, 2 days. (Red \$2101.14, 52%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : A/Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Other:

TOTAL

Report Filed: TP

Long Sum: 1950