

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

INV No. AC2206712

INV Date 01/11/2022

Reference CS/EQI22010161/Uvy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. FBT 6408P

Insured Veh. SLX 3183S

Claim No. DM22HO01748

Policy No. DMPPHQ22-006590

Accident Date 06/10/2022

Inspection Date 13/10/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Internation	ale Des Experts En Auton	nobile							
	EQ INSURANCE C	OMPANY LTD	Ref:	CS/EQI22010161/Uvy3e2							
	5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSII	OCK	Date:								
			Code	: EQI							
1.		Policy Particulars :	- THIRD PARTY CLA	IM							
	Insured Veh.	SLX 3183S	Veh. Inspected	FBT 6408P							
	Policy No.	DMPPHQ22-006590	Coverage (\$)	0.00							
	Claim No.	DM22HO01748	Excess (\$)	0.00							
	Assign From	NEO JIE SI	Assign Date	13/10/2022							
2.		Vehicle Partic	ulars & Condition								
	Make & Model	YAMAHA T150	c.c	150							
	Engine No.	HIDDEN	Year of Reg.	2022							
	Chassis No.	MH3UG131000002100	Colour	BLUE							
	Odometer	10310 KM	Steering	IN ORDER							
	Brakes	IN ORDER	Modification	SPORTS RIM							
	General	GOOD									
3.	Conditions of Tyres										
		Size	Make	Balance							
	R/H Front Tyre	90-80-17	IRC	7 mm							
	L/H Front Tyre			mm							
	R/H Rear Tyre	120-70-17	IRC	7 mm							
	L/H Rear Tyre			mm							
4.	Description of Damages										
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT PORTION AND N/S	BODY.							
	DAMAGES SEE DE	ETAILS.									
5.		General	Information								
	Accident Date	06/10/2022	Inspection Date	13/10/2022							
	Survey held at	2ND AUTO PTE LTD									
		15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808									
5a.		Re	emarks								
		N WAS CONDUCTED ON A"WITI E TO YOUR INSTRUCTIONS, WI									
5b.		Estimate I	Days of Repair								
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	4 Wor	king Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 6408P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER ASSY	CUT / CRACKED	180.00	90.00
1	FRONT SIDE COVER LH	CRACKED	160.00	160.00
1	FRONT SIDE COVER RH	NOT NECESSARY	160.00	-
1	FRONT COWLING ASSY	CRACKED	220.00	220.00
1	FRONT HEADLAMP ASSY	CRACKED	500.00	380.00
1	FRONT SIGNAL LAMP LH	CRACKED	120.00	120.00
1	FRONT PILOT LAMP LH	CRACKED	120.00	120.00
1	FRONT FORK ASSY LH	TO REPAIR SEE LABOUR	350.00	-
1	FRONT FORK ASSY RH	TO REPAIR SEE LABOUR	350.00	-
1	FRONT SIDE COVER DECAL STICKERS	NECESSARY	80.00	80.00
1	SIDE COVER LH	CRACKED	100.00	100.00
1	FRONT FOOTREST LH	CUT	48.00	48.00
1	FRONT VIEW MIRROR LH	SCRATCHED	50.00	50.00
1	HANDLE BAR END LH	CUT	30.00	30.00
1	FAIRING INNER COVER	CRACKED	165.00	165.00
1	FRONT STEM BRACKET	BENT	160.00	160.00
	LESS 10% DISCOUNT		-	-172.30
			2,793.00	1,550.70
	SPECIAL NETT ITEMS			
1	FRONT CENTER COMPARTMENT BOX (SN)	CRACKED	200.00	40.00
1	REAR STORAGE TOP BOX (SN)	CUT	300.00	250.00
			500.00	290.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS .JOB ALLOWANCE.	NOT NECESSARY	1,600.00	-
	TO CHECK FRONT LIGHTING AND WIRING.	NOT NECESSARY	100.00	-
	TO REMOVE AND INSTALL GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	120.00	-
	TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS .	NOT NECESSARY	300.00	-

Report Ref No. CS/EQI22010161/Uvy3e2



(TO ITS PRE-ACCIDENT CONDITION)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND INSTALL FRONT FENDER ASSY .	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL FRONT SIDE COVER ASSY .	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL FRONT SIGNAL LAMP .	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL FRONT CENTER COMPARTMENT BOX.	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL FRONT FORK ASSY .		180.00	80.00
	TO REMOVE AND INSTALL FRONT COWLING ASSY .	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL REAR STORAGE TOP BOX.	NOT NECESSARY	180.00	-
	LABOUR CHARGE FOR REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY LH AND FRONT FORK ASSY RH.		400.00	260.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	350.00	-
			4,130.00	340.00
	GRAND TOTAL		7,423.00	2,180.70
	RECOMMENDED COST OF LUMP SUM REPAIRS			1,700.00

Report Ref No. CS/EQI22010161/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/10/2022 18:01 (SGT) Reported by Date of Accident 06/10/2022 13:53 (SGT) Exact Location of Accident Singapore Additional Location Information CROSS JUNCTION OF MAUDE ROAD AND TOWNSHEND ROAD Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBT6408P

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner SLS BEARINGS (SINGAPORE) PTE LTD Company Reg No 1972500761H Email Address JESSICA.T@SLSBEARINGS.COM.SG Mobile Phone No (Phone) +65-96318840

Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Yamaha Model Jupiter t150 Variant

Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Motorcycle Transmission

Auto CC 1500

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number D300573862 VMC

DRIVER

Name of Driver **TEU MEEI PYNG** Passport No/FIN F7183223Q Date Of Birth 08/02/1972 Occupation Outdoor

Date Of Driving Pass 03/06/2019 Driving experience 3 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-96790233 Alt. Phone Number Email Address 1972TEU.TEU951680@GMAIL.COM Address 738 YISHUN ST 72 #12-155 S760738 Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Motorcyclist Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT SEE ATTACHED REPORT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SLX3183S Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car

ROSS VELANTINE ERROL

(Phone) +65-81880909

Name of Driver

Contact Number

Address	
Address complement	
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TEU MEEI PYNG
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	FBT6408P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to appead up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for Investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties,
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of;

(i) processing, handling and/or dealing with my dalms including the settlement of the claims and any necessary investigations relating to the claims:

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents

SLS BEARINGS (S) PTE. LTD.

322 Jalan Besar Singapore 208980 13 -1 = 7 M.


TEL 6292 5586 FAX 6294 1270 13 10 1 Co. Reg. No 1972007 411 7 10 2V GST Reg No M2-001 3869

Policyholder's Signature LB ate & Time Actual Driver's Signature (if driver is not the policyholder) / Date & Time

07/10/2022 1155AM

Witnessed by Recording Capital Personnel (Name as in NRICAD rain)

Sketch Plan



CS CamScanner

- 1	Ot stated	date	and	time	I	s travell	ly stre	aright or	Townsho	nd Ro
									chiagota	
line a	illas b	oled w	ith mu	_ve'	hide.					
					-					
				les :	_t					
								10 111=		
						251				
			-							
Declarati	e the foregoin	g particular	are true	in every	respect,					
RINGS (S Besar Sing 92 5566 FA	x 6294 1270	Det .	=pm	/	M	7			(329) 5	00K 5
Reg. No. 19) Reg. No. M2-	20000	7/101	M	_	Y		2022 16		essed by Bego	15

vJun2022

CS CamScanner



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBT 6408P

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBT 6408P

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBT 6408P

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





