

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

<input checked="" type="checkbox"/> N/S	<input checked="" type="checkbox"/> O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMK 21004 Yr Regn: 29/3/19  
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: BMW 520i c.c. 1998  
 Colour: White A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA  
 Sp. Reading: 37360 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBAJA12010B321285  
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt  
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or \_\_\_\_\_  
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or \_\_\_\_\_  
 Modl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225/45R18  
 R: 17  
 BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 10/10/22 D.O.I. 13/10/22  
 Survey held at Performance Motor  
 Des. of Damages: Frt / Rear / O/S ☒ N/S / ☐ UIC / ☐ Rooftop or \_\_\_\_\_  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-181X

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$I

Photos

Others

TOTAL

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Lump Sum / L.B.H. (\$) \_\_\_\_\_

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 63622  
Date Estimated : 11/10/2022  
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Chua Jian Construction Pte. Ltd.  
10 Jalan Besar  
#10-04 Sim Lim Tower

Singapore 208787

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK2100U	WBAJA12010BJ21285	29/03/2019	520i	32966

DESCRIPTION	VALUE
To replace left front fender, left front door, left rear door, left side skirting and make good rear left fender and rear bumper. <i>3 x 850</i>	<i>2559</i> 8,500.00
To respray left front fender, left front door, left rear door, left rear fender, rear bumper and left side skirting. <i>4293</i>	5,404.00
To carry out body cavity preservation. (Per panel). <i>336</i>	354.00
To check electrical wiring <i>168</i>	177.00
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (2 doors). <i>1009</i>	1,062.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x). <i>504</i>	531.00
To replace tyre and wheel rim including balancing. (1x).	94.00
Sundries.	150.00

Total Labour 1: 16,272.00

DESCRIPTION	QTY	PRIC	VALUE
LIGHT ALLOY RIM 8JX18 W SPK 632 <i>cut</i>	1	1,045.30	1,045.30
FRT LH DOOR ALUMINIUM <i>00</i>	1	1,910.15	1,910.15
REAR LH DOOR ALUMINIUM <i>00</i>	1	1,910.15	1,910.15
FRT LH SIDE PANEL ALUMINIUM <i>X</i>	1	952.05	952.05
LH SILL TRIM PRIMED <i>X R</i>	1	433.70	433.70

Total Parts : 6,251.35



**Performance Motors Limited**

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 63622**  
 Date Estimated : **11/10/2022**  
 Prepared By : **Jack Ng Guo Ming**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK2100U	WBAJA12010BJ21285	29/03/2019	520i	32966

Steve (LKK)  
 13/9/22, 4.12pm

ON-11 HL

Excess-?

P/P

by RL y  
 8 d p

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	16,272.00
Parts	:	6,251.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,576.63
Grand Total	:	<b>24,099.98</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 10/10/2022 18:16 (SGT)  
Reported by ..... Both  
Date of Accident ..... 10/10/2022 12:00 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... TOWNER ROAD  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMK2100U

#### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... CHUA JIAN CONSTRUCTION PTE LTD  
Company Reg No ..... 2XXXXX468D  
Email Address ..... mistylin@gmail.com  
Mobile Phone No ..... (Phone) +65-96662657  
Alternative Phone No ..... -

#### VEHICLE PARTICULARS

Manufacturer ..... BMW  
Model ..... 520i  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1998

#### INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance (Singapore) Pte. Ltd.  
Policy Number / Cover Note Number ..... -

#### DRIVER

Name of Driver ..... WANG JINRUI  
NRIC No ..... SXXXX007I  
Date Of Birth ..... 11/08/1956  
Occupation ..... Indoor

Date Of Driving Pass	30/04/2019
Driving experience	3 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91072397
Alt. Phone Number	-
Email Address	mistylin@gmail.com
Address	BLK 10C BENDEMEER ROAD #28-131
Address complement	-
Postcode	333010
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Kampong Java Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-1800295999
Alt. Police Station Phone No	(Fax) +65-63913442
Police Station Address	21 Kampong Java Road Singapore 228892
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACH

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SLX9248A
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LOW HEE SIAH
NRIC No	SXXXX109I
Contact Number	(Phone) +65-97979477
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-




Refer to Police Report. -

I/We declare the foregoing particulars are true in every respect.

1/We declare the foregoing particulars  
  
 Policy No. \_\_\_\_\_ Signature \_\_\_\_\_  
 Date & Time: 10/10/2022 1600

Driver's Signature \_\_\_\_\_  
(if driver is not the policyholder)  
Date & Time: \_\_\_\_\_


**Jack Ng Guoming**  
 Performance Motors Limited  
 303 Alexandra Road  
 Sims Dairy Performance Centre  
 Singapore 159941

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

10/10/2022

1600

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NNIC/IN No.:

Jack Ng Guoming  
Performance Motors Limited  
303 Alexandre Road  
Sime Darby Performance Centre  
Singapore 158941





**SINGAPORE  
POLICE FORCE**



T/20221010/2058

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999

1 of 4  
Report No. T/20221010/2058

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 10/10/2022 14:44		Vide Report No.:		Station Diary No.: 52	
<b>Informant's Particulars</b>					
Name of Informant: WANG JINRUI			Address: APT BLK 10C BENDEMEER ROAD #28-131 SINGAPORE 333010		
ID Type / ID No.: NRIC NO / S26610071			Contact No.: Home/Office: Mobile: 91072397		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 66	Date of Birth: 11/08/1956	Type of Informant: Driver		
Race: Chinese		Language: Chinese		Institution / School Name:	
Occupation: Company director		Driving Licence Information: Class: 3A		Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 10/10/2022 12:00	Type of Location: Car Park
Location:  TOWNER ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLX9248A	Car	HONDA	Civic	Silver	Slightly Damaged	0
SMK2100U	Car	BMW	520i	White	Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20221010/2058

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999

2 of 4

Report No. T/20221010/2058

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	LOW HEE SIAH	ID No.	S6844109I
Related Vehicle	SLX9248A (Car)	Contact No.	97979477
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	WANG JINRUI	ID No.	S2661007I
Related Vehicle	SMK2100U (Car)	Contact No.	91072397
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 10/10/2022 at about 1200hrs, I was driving my vehicle SMK2100U in the OSCP of Block 104 Towner Rd. While I was making my way out of the carpark with my vehicle, a vehicle bearing car plate number SLX9248A that was parked in carpark lot number 353, had suddenly accelerated forward and collided against the left side of my vehicle while my vehicle was moving. Upon the collision, I immediately stopped my vehicle on the spot and alighted to make a check on the damages. The driver of SLX9248A then reversed his vehicle back into the lot before he alights from his vehicle.

My vehicle suffered multiple scratches, dents and paint peel damages acrossed the left side of my vehicle, including the front left passenger door, rear left passenger door, left side-skirt, rear left fender, rear left bumper and the rims.

I then exchanged personal particulars with the driver and both of us had agreed to report the accident to our respective insurance company for damages claims.

During the accident, my grand-daughter was my only passenger, whereas the driver of vehicle SLX9248A did not have any passenger. Fortunately, none of us was hurt nor injured in the accident.

I am lodging this traffic accident report for insurance claims and record purposes only.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999



T/20221010/2058

3 of 4

Report No. T/20221010/2058

CONTINUATION OF REPORT





**SINGAPORE  
POLICE FORCE**



T/20221010/2058

Police Station Of Origin:  
Kampong Java N.P.C  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-2959999

4 of 4

Report No. T/20221010/2058

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:  
E /  
SGT 3 GUO JUNLIANG

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIA /  
SI ANG YI TING, STEPHANIE  
Contact No.: 65476414

Signature Of Informant:

Date/Time:  
10/10/2022 14:44

Classification Of Case:

NP168