



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22010163/Tny3m4 Date: 31/03/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJW 1027C	Veh. Inspected	SLD 8712M	
Policy No.	P10715384R00	Coverage (\$)	0.00	
Claim No.	C10018021/JY	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	13/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN X-TRAIL 2.0	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1JANT32Z0002145	Colour	BLUE	
Odometer	117161 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/10/2022	Inspection Date	13/10/2022	
Survey held at	PROMPT AUTO SOLUTIONS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	