

ASS. REC. BY:

REF:

C72 / 22010167/KV

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Got BZ

23/11 / 1 Pm @ 3100d Carhu

Veh No:

FBP 79306 Yr Regn: 06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Aerox c.c. 155

Colour:

Red / Grey A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH 3SG 464 OK J 049876

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/10/2022 14:50 (SGT)
Reported by	Both
Date of Accident	09/10/2022 15:30 (SGT)
Exact Location of Accident	Tampines St. 11, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP7930L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	THEAN CHUAN DEE
NRIC No	SXXXX930D
Email Address	chuandee54@gmail.com
Mobile Phone No	(Phone) +65-91598871
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	AEROX GDR155A CVT AB
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Manual
CC	155

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	300585000

DRIVER

Name of Driver	THEAN CHUAN DEE
NRIC No	SXXXX930D
Date Of Birth	14/12/1954
Occupation	Indoor

Date Of Driving Pass	12/10/1977
Driving experience	45 YEARS
Gender	Male
Mobile Number	(Phone) +65-91598871
Alt. Phone Number	-
Email Address	chuandee54@gmail.com
Address	BLK 161 TAMPINES ST 12 #09-215
Address complement	-
Postcode	521161
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tampines Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005871999
Alt. Police Station Phone No	(Fax) +65-65871699
Police Station Address	6 Tampines Ave 4 Singapore 529682
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

NOTE: VEHICLE REPAIR AT OWNER W/SHOP.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW5109Z
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MUHAMMAD FAZLI BIN SUN'AN
-	SXXXX016F
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	THEAN CHUAN DEE
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	FBP7930L
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

Refer to police report

duandee54@gmail.com

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Phonice
Whe

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



SINGAPORE POLICE FORCE



T/20221010/2008

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20221010/2008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/10/2022 09:22	Vide Report No.:	Station Diary No.: 15
--	------------------	--------------------------

Informant's Particulars

Name of Informant: THEAN CHUAN DEE			Address: APT BLK 161 TAMPINES STREET 12 #09-215 SINGAPORE 521161		
ID Type / ID No.: NRIC NO / S2007930D			Contact No.: Home/Office: Mobile: 91598871		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 67	Date of Birth: 14/12/1954	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: Carpenter			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

General Information of the Accident:				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/10/2022 15:30	Type of Location: Straight Road
Location: TAMPINES STREET 11				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBP7930L	Motorcycle	YAMAHA	AEROX GDR155A CVT ABS	Red	Slightly Damaged	0
SJW5109Z	Car					1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20221010/2008

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3

Report No. T/20221010/2008

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBP7930L	MSIG INSURANCE (SINGAPORE) PTE. LTD.	300585000	17/06/2022	16/06/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	THEAN CHUAN DEE	ID No.	S2007930D
Related Vehicle	FBP7930L (Motorcycle)	Contact No.	91598871
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	10/10/2022	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	MUHAMMAD FAZLI BIN SUN'AN	ID No.	S8203016F
Related Vehicle	SJW5109Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/10/2022 at 1530hrs, I was riding my motorbike (FBP7930L) along Tampines Street 11. While I was riding past the carpark of Blk 102 Tampines Street 11, a car (SJW5109Z) suddenly drove out of the carpark and tried to make a right turn. I tried to stop but to no avail and collided onto the right side of the car. We exchange particulars and Traffic Police came to scene shortly after. As I was feeling unwell after the impact, I was conveyed by the ambulance to CGH and receive a 5 days MC.



**SINGAPORE
POLICE FORCE**



T/20221010/2008

3 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20221010/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

G /

SGT 2 WONG QING JIE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

10/10/2022 09:22

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMED FEROZ BIN HUSSIEN

Contact No.: 65476206

Classification Of Case:

NP168

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Not Notified
11/10/22
Returning After Paint
4 days

Date: 12 October 2022

To : LKK

Attn :

Tel :

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

ACCIDENT DATE: 9 October 2022

	Description	Qty	Quotation \$
1	Handle Bar ?	1	
2	Balancer Old L	1 set	
3	Mirror Old L	1 set	
4	Brake Lever R L	1	
5	Front V Panel M/L	1	
6	Head Lamp Assy R	1	
7	Signal Light L/RH S X	1 set	
8	Front Mudguard R X	1	
9	Front RH Panel M/L	1	
10	Front LH Panel ?	1	
11	Head Lamp Lower Guard C R	1	
12	Fork Tube ?	1 set	
13	Fork Bracket ?	1	
14	Centre Leg Shield ?	1	
15	RH Leg Shield ?	1	
16	Front Lower Panel RH W	1	
17	Rear Tail Panel - RH R X	1	
18	Exhaust Guard R/L	1	
19	Exhaust Pipe R X	1	
20	Dash Board Panel ?	1	
21	Dash Board Lid ?	1	
22	RH Centre V Panel ?	1	
23	Front Rim S X	1	
24	Brake Disc S X	1	

Sub-Total

0.00

Less 10%

0.00

Sub-Total

0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

Nett items

1	Rear box	7	
2	Towing fee		40.00 35/
3	Remove & replace parts, align & etc		280.00 150/
4	Remove & replace fork tube, fork oil seal, & top up fork oil		120.00 7
5	Body decal sticker		150.00 —
6	Alignment to frontal body		250.00 100/

Sub-Total 840.00

Nett Total 840.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any alleged restriction(s) is allowed
- Application for (s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged: _____
Signature: _____
Date: _____

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Not Asks
11 Pp &
Returning After Paint
4 days
Kenneth (61616)

Date: 12 October 2022

To : LKK

Attn : Mr. Kenneth

Tel :

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

ACCIDENT DATE: 9 October 2022

	Description	Qty	Quotation \$
1	Handle Bar	1	
2	Balancer	1 set	
3	Mirror	1 set	
4	Brake Lever	1	
5	Front V Panel	1	
6	Head Lamp Assy	1	
7	Signal Light L/RH	1 set	
8	Front Mudguard	1	
9	Front RH Panel	1	
10	Front LH Panel	1	
11	Head Lamp Lower Guard	1	
12	Fork Tube	1 set	
13	Fork Bracket	1	
14	Centre Leg Shield	1	
15	RH Leg Shield	1	
16	Front Lower Panel RH	1	
17	Rear Tail Panel - RH	1	
18	Exhaust Guard	1	
19	Exhaust Pipe	1	
20	Dash Board Panel	1	
21	Dash Board Lid	1	
22	RH Centre V Panel	1	
23	Front Rim	1	
24	Brake Disc	1	
Sub-Total			0.00
Less 10%			0.00
Sub-Total			0.00

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

Nett items

1	Rear box		
2	Towing fee	40.00	35/
3	Remove & replace parts, align & etc	280.00	150/
4	Remove & replace fork tube, fork oil seal, & top up fork oil	120.00	7
5	Body decal sticker	150.00	—
6	Alignment to frontal body	250.00	100/

Sub-Total 840.00

Nett Total 840.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17 October 2022

To : LKK

Attn : Kenneth

Tel : 96910663

VEHICLE NO : FBP 7930L
ACCIDENT DATE: 9 October 2022

Yamaha Aerox GDR 155A

Supplementary Items:

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Board Footrest L/RH ds ✓	1 2	
2 Mole Side Cover L/RH ds ✓	1 2	
3 Body Centre Panel ✗	1 2 X	
4 Right Panel -B68.FB35V-00 ✓	1	
	Sub-Total	0.00
	Less 10%	0.00
	Total	0.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Not Authorized
L1 By @ 3100h
Repairing After Painting
4 days

Date: 12 October 2022

To : LKK

Attn : Kenneth

Tel : 96910663

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

ACCIDENT DATE: 9 October 2022

Description	Qty	Quotation \$
1 Handle Bar <i>145</i>	1	<i>B1</i> 165.00 <i>✓</i>
2 Balancer <i>80</i>	1 set	<i>old B1</i> 120.00 <i>✓</i>
3 Mirror	1 set	<i>old B1</i> 140.00 <i>✓</i>
4 Brake Lever	1	<i>new</i> 75.00 <i>✓</i>
5 Front V Panel	1	<i>my cm</i> 180.00 <i>✓</i>
6 Head Lamp Assy <i>499</i>	1	<i>B1</i> 550.00 <i>✓</i>
7 Signal Light L/RH	1 set	<i>new</i> 150.00 <i>X</i>
8 Front Mudguard	1	<i>new</i> 250.00 <i>X</i>
9 Front RH Panel	1	<i>my cm</i> 180.00 <i>✓</i>
10 Front LH Panel	1	<i>my cm</i> 180.00 <i>✓</i>
11 Head Lamp Lower Guard	1	<i>cm</i> 220.00 <i>✓</i>
12 Fork Tube	1 set	<i>B1</i> 550.00 <i>✓</i>
13 Fork Bracket	1	<i>old</i> 280.00 <i>✓</i>
14 Centre Leg Shield	1	<i>cm</i> 180.00 <i>✓</i>
15 RH Leg Shield	1	<i>new</i> 180.00 <i>X</i>
16 Front Lower Panel RH	1	<i>new</i> 190.00 <i>✓</i>
17 Rear Tail Panel - RH	1	<i>new</i> 220.00 <i>X</i>
18 Exhaust Guard	1	<i>old B1</i> 150.00 <i>✓</i>
19 Exhaust Pipe	1	<i>new</i> 1,350.00 <i>X</i>
20 Dash Board Panel	1	<i>my cm</i> 180.00 <i>✓</i>
21 Dash Board Lid <i>220</i>	1	<i>cm</i> 280.00 <i>✓</i>
22 RH Centre V Panel	1	<i>my cm</i> 180.00 <i>✓</i>
23 Front Rim	1	<i>new</i> 350.00 <i>X</i>
24 Brake Disc	1	<i>new</i> 320.00 <i>X</i>

Sub-Total 6,620.00
Less 10% 662.00
Sub-Total 5,958.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

Nett items

- 1 Rear box
- 2 Towing fee
- 3 Remove & replace parts, align & etc
- 4 Remove & replace fork tube, fork oil seal,
& top up fork oil
- 5 Body decal sticker
- 6 Alignment to frontal body

Sur	320.00	X
	40.00	35/-
	280.00	750/-
	120.00	80/-
m	150.00	✓
	250.00	100/-

Sub-Total	1,160.00
Nett Total	7,118.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17 October 2022

To : LKK

Attn : Kenneth

Tel : 96910663

VEHICLE NO : FBP 7930L

Yamaha Aerox GDR 155A

ACCIDENT DATE: 9 October 2022

Supplementary Items:

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Board Footrest L/RH	2	280.00
2 Mole Side Cover L/RH	2	280.00
3 Body Centre Panel	2	190.00
4 Right Panel	1	180.00
Sub-Total		930.00
Less 10%		93.00
Total		837.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD