

China (Lisun)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.09.2022

REPAIR ESTIMATE

Time: 15:01:22

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305531602
REGN NO : SHD7111B
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.11.2016
DATE/TIME IN : 28.09.2022 09:50
ACCIDENT DATE : 28.09.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0593-G	PANEL ASSY-FR DR LH#	1	2,707.70	20.00	2,166.16	ht
0002	04-01-0103-0730-G	COVER-FR DR O/S HDL DRIV	1	32.60	20.00	26.08	mis
0003	04-01-0103-0728-G	HANDLE ASSY-DR O/S	1	132.30	20.00	105.84	ca
0004	04-01-0103-0722-G	LATCH ASSY-FR DR LH	1	290.80	20.00	232.64	x
0005	28-01-0103-0003-A	FRT DOOR LOGO CTPL	1 N	75.00	2.00-	75.00	at

SUB-TOTAL : 2,605.72

JOB NATURE

0000	PB	PANEL BEATING	400.00	280 280
0001	SP	SPRAYPAINT CHARGE	300.00	250

SUB-TOTAL : 700.00

TOTAL : 3,305.72

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Tanpin 97995749
wp 28/9/22 24pm
cls Newy after repair
tanpin @ Manta.com
22 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Acc: _____
Sign: _____
Date: _____

Item: ARC Repair TP(CLSO)1

JOB CARD Sales Order:


JC No: 805531602

CUSTOMER NO. CUSTOMER: COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS: 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO: SHD7111B	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 28.09.2022 09:50
	YR OF MANU. 10.11.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMHU095480	COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 28.09.2022
DURE: 3P.28.09.22

NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Confirmation Slip

Exit Pass

No.: **SHD7111B**

JU CHINA

Vehicle No.:

SHD7111B

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard