

China (Usam)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.09.2022

Time: 15:01:22

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305531602
REGN NO : SHD7111B
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.11.2016
DATE/TIME IN : 28.09.2022 09:50
ACCIDENT DATE : 28.09.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0593-G	PANEL ASSY-FR DR LH#	1	2,707.70	20.00	2,166.16	ht	
0002	04-01-0103-0730-G	COVER-FR DR O/S HDL DRIV	1	32.60	20.00	26.08	mis	
0003	04-01-0103-0728-G	HANDLE ASSY-DR O/S	1	132.30	20.00	105.84	car	
0004	04-01-0103-0722-G	LATCH ASSY-FR DR LH	1	290.80	20.00	232.64	x un.	2872.60
0005	28-01-0103-0003-A	FRT DOOR LOGO CTPL	1 N	75.00	2.00	75.00	ad	2298.08 SW 75

SUB-TOTAL : 2,605.72

2373.08

JOB NATURE

0000	PB	PANEL BEATING	400.00	280 280		
0001	SP	SPRAYPAINT CHARGE	300.00	250	530	

SUB-TOTAL : 700.00

TOTAL : 3,305.72

2903.08

11/23/2300

02 days

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Tanfik 97995749
wp 28/9/22 c/p
c/s Reorg after repair
Tanfik e/Manu in
02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is a ... from Insurance Company

ack: _____
Signature: _____
Date: _____