

ASS. REC. BY:

REF:

CS3/ARM22010172/Scy3

ASSIGNMENT

PRS

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Bike Image motor

of

Insured: AXA

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 10 K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Est Repair Cost
: \$2000-2500 /-

yearly: 1400

mv: 10K

NU: 7K

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Veh No:

FBR 594J

Yr Regn: 17 Feb 2020

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha F 25150

c.c. 149

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

15190

T/Radio: Insured / Std / NI / NA

Eng/No:

ME1R644B8K0050909

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / ARim or

Tyre Size:

F: 100/80-17

R: 140/60-17B

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CEAT

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

-

mm

L/Bal.

-

mm

D.O.A.

09/10/22

D.O.I.

13/10/22

Survey held at

Bike Image motor

Des. of Damages

☒ Fvt

☒ Rear

☐ O/S

☒ N/S

☐ U/C

☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.