

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22010215/Rwy3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 23/11/2022 SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SKW 824M SHA 4513K Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S2M04CS8 Excess (\$) 0.00 **LOH CYNTHIA Assign Date** 13/10/2022 Assign From **Vehicle Particulars & Condition** 2. **HYUNDAI ELANTRA 1.6 AT** Make & Model 1591 c.c HIDDEN 2015 Engine No. Year of Reg. KMHDH41CMGU641714 **GREY** Chassis No. Colour Odometer 146015 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/55 R16 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195/55 R16 6 mm 195/55 R16 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195/55 R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 02/01/2022 15/11/2022 ( 03:10 PM ) Inspect Date / Time Accident Date HENG YAP SENG AUTO SERVICE Survey held at 160 SIN MING DRIVE #08-13 SIN MING AUTOCITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

Report Ref No. CS3/ASM22010215/Rwy3m4

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

**Estimate Days of Repair** 

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

ESTIMATED NORMAL PERIOD FOR REPAIR:

**Inspected By** 

**Automotive Assessor** 

5b.

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DEOD A. 1 - O - - - 1 (- - 1 OAE | 1 - - - - 1 A - - - - 1 - - - -

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

8 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser