

Service Request Details

Claim	S2M04CS8
Reference	CS3/ASM22010215/Rwy3m4 
Loss Date	2 January 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	13 Oct 2022 10:58:11 AM
Request Date	13 October 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SKW824M
Vehicle	
Registration #	
Make	TPVD - HYUNDAI
Model	ELANTRA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2207234.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	23 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	23 November 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 November 2022
 SKW 824M Preliminary Advice_1.6cc/8days/\$5K-\$6K.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 November 2022
 TP PRI.msg.msg	Letters and Correspondence	Workshop	PODUVAL Akash	13 October 2022
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL Akash	13 October 2022
 TP GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	13 October 2022
 REPLY FROM TP.msg.msg	Letters and Correspondence	Third Party	KUMAR Shailendra	13 October 2022

