

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22010219/Acy3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	23/12/2022	
			C	Code:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLM 6154P	Veh. Inspected		SKC 734U	
	Policy No.	P10536544R01	Coverage (\$)		0.00	
	Claim No.	C10018065/JY	Excess (\$)		0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date		14/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VOXY	c.c		1986	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	ZRR700136903	Colour		BLACK	
	Odometer	382549 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	CONTINENTAL		6 mm	
	L/H Front Tyre	215/60 R16	CONTINENTAL		6 mm	
	R/H Rear Tyre	215/60 R16	CONTINENTAL		6 mm	
	L/H Rear Tyre	215/60 R16	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/10/2022	Inspection Date		14/10/2022	
	Survey held at	JL PERFECT AUTOWORK PTE LTD				
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: