



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HL ASSURANCE PTE LTD 11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057			Ref: CS/HLA22010258/Uwy3m4 Date: 02/11/2022 Code: HLA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	UNITED E & P PTE LTD		Veh. Inspected	SMX 3733T
Policy No.			Coverage (\$)	0.00
Claim No.	PLC01062/JG		Excess (\$)	0.00
Assign From	LYNN ROMEO		Assign Date	17/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL (A)		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	RU11113350		Colour	WHITE
Odometer	74873 KM		Steering	AFFECTED
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre		215/60 R16	LASSA	6 mm
L/H Front Tyre		215/60 R16	LASSA	6 mm
R/H Rear Tyre		215/60 R16	LASSA	6 mm
L/H Rear Tyre		215/60 R16	LASSA	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S & N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/10/2022		Inspection Date	17/10/2022
Survey held at	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	