

From:

Date:

Estimated Cost:

OD ☒ TP ☒ / S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Yong Sing Motor Works

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	N/S	O/S

Bal. or Market Value: \$6500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJE3250E

Yr Regn: 22 Apr/2008

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 c.c 1598

Colour: Silver

A/C: Insured / Std / NI / NA

Sp.Reading: 182469

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053ZEE106105804 *

Gen. Cond ☒ Good ☐ Fair / Poor / Burnt

Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/R or

Tyre Size: F: 195/65R15 DOUBLRSTAR/WESTLAKE

R: // LINGLONG

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 17-10-2022

Survey held at

W/S

12PM

Des. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1000 - \$2000

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : W/Weekend (\$

\$ + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Quid/MP/...