

(06/11/21)

ASS. REC. BY:

REF:

PRS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hifter Auto garage

of _____

Insured: ASm

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 70k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 8008H Yr Regn: 14 JUN 2016Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 216 D GT c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 132750 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAZE320705B44866Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A Rim orTyre Size: F: 225/50 R17R: 225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FireLIL

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/10/22 D.O.I. 18/10/22Survey held at Shifter Auto garageDes. of Damages Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Est Repair cost

- \$ 13K - 18K / -

yearly: 15K

mv: 70k

INV: 66k

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

1181

Vehicle Details

Vehicle No.:

SLE8008H

Vehicle to be Exported:

Yes

Intended Deregistration Date:

18 Oct 2022

Vehicle Make:

B.M.W.

Vehicle Model:

216D GRAN TOURER LED NAV 7 SEATER

Primary Colour:

Black

Manufacturing Year:

2016

Engine No.:

30719519B37C15A

Chassis No.:

WBA2E320705B44866

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$30,861.00

Original Registration Date:

(14 Jun 2016)

First Registration Date:

14 Jun 2016

Transfer Count:

0

Actual ARF Paid:

\$25,206.00 + 15% = 12603

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Jun 2026

PARF Rebate Amount:

\$16,383.00

Intended COE Rebate Details

COE Expiry Date:

(13 Jun 2026)

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$53,694.00

COE Rebate Amount:

\$19,621.00

Total Rebate Amount:

\$36,004.00

The information contained herein is correct as at 18 Oct 2022

DUA: 10110122

Balance: 328m - 440K

yearly: 15700 /

mv: 70169 - 70K

NV: 66565 - 66K

