



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Ref: CS/GAI22010269/Uqy3e2

Date: 03/11/2022

Code: GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 301S	Veh. Inspected	SKS 3787M
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004245	Excess (\$)	0.00
Assign From	JANELLE TAN	Assign Date	17/10/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11017780	Colour	RED
Odometer	101675 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	PREMIO	6 mm
L/H Front Tyre	215/60 R16	PREMIO	6 mm
R/H Rear Tyre	215/60 R16	PREMIO	6 mm
L/H Rear Tyre	215/60 R16	PREMIO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/10/2022	Inspection Date	25/10/2022
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**