



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS3/FCI22003674/Tqy3e2-1 Date: 09/11/2022 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XD 3549J	Veh. Inspected	GBK 4427U
Policy No.		Coverage (\$)	0.00
Claim No.	D22001151MCVT	Excess (\$)	0.00
Assign From	ESTHER LIM	Assign Date	17/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV200 1.6DX A	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	VM20142457	Colour	SILVER
Odometer	21096 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	18/04/2022	Inspection Date	21/04/2022
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	