

CC4/ASM 22010304/TP93.

ASIS REC BY: T. J. M.

Vehicle Condition Report

ASSIGNMENT

From: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Number

Date / Time

Action / Instruction

Battery weak.

Veh No: SHB 4451A

Yr Regn: 2021 Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai

C.C. 1580

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C85 / CVLH 192 789

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: (Nil) / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Weslake

Front

Rear

R/Bal. 6 mm

mm

R/Bal. 6 mm

mm

L/Bal. 6 mm

mm

L/Bal. 6 mm

mm

D.O.A. _____

D.O.I. 17/10/22

Survey held at Cyber City

Des. of Damages: Frt / Rear / O/S / N/S / U/S / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

ATA (P/P)
Date: 14.10.2022
Time: 14:41:41
Page: 1
JH

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305533028
REGN NO : SHB4451A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 29.01.2021
DATE/TIME IN : 14.10.2022 13:45
ACCIDENT DATE : 13.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0595-G	PANEL ASSY-REAR DOOR RH#	1	2,147.90	20.00	1,718.32	bt /
0002 04-01-0104-2470-G	MOULDING ASSY-W/LINE RR D	1	125.30	20.00	100.24	cut /
0003 28-01-9999-2032-A	ZIG BOOK NOW APP LOGO REA	1 N	80.00	2.00-	80.00	cut /
0004 03-01-0104-2061-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	cut /

SUB-TOTAL : 2,175.68

JOB NATURE

0000 PB	PANEL BEATING	800.00	525
0001 SP	SPRAYPAINT CHARGE	1000.00	600
0002 20-204	REMOVE/REFIX UPHOLSTERY REAR	100.00	60.
0003 L	TRANSFER DOOR PARTS	120.00	60.

SUB-TOTAL : 2,020.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305533028
REGN NO : SHB4451A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 29.01.2021
DATE/TIME IN : 14.10.2022 13:4
ACCIDENT DATE : 13.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,195.68

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

Tanphi 67495749
WP 17/10/22 @ 3pm
p/p Resury before paint
tanphi @ lkk auto-con
• 3 delays

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
329 Ubi Road Singapore 708699

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 14.10.2022 14:46

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5027456

JC NO305533028

OWNER

AS COMFORT TRANSPORTATION PTE LTD
FOMER NO 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO:

SHB4451A

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 14.10.2022 13:45

YR OF MANU

29.01.2021

TARGET DATE

CHASSIS CODE

KMHC851CVLU192789


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 13.10.2022
ATURE: 3P.13.10.22

/NO	LABOR CODE
0000	PB
00060	SP
00070	20-204
00080	L

DESCRIPTION
PANEL BEATING
SPRAYPAINT CHARGE
REMOVE/REFIX UPHOLSTERY REAR
TRANSFER DOOR PARTS



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

SHB4451A

JU AXA

Exit Pass

Vehicle No.:

SHB4451A

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard