

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 14.10.2022

Time: 14:41:41

Page: 1

AKA (p/p)
JH

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305533028
REGN NO : SHB4451A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 29.01.2021
DATE/TIME IN : 14.10.2022 13:45
ACCIDENT DATE : 13.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0595-G	PANEL ASSY-REAR DOOR RH#	1	2,147.90	20.00	1,718.32	bt/	
0002 04-01-0104-2470-G	MOULDING ASSY-W/LINE RR D	1	125.30	20.00	100.24	cut	
0003 28-01-9999-2032-A	ZIG BOOK NOW APP LOGO REA	1 N	80.00	2.00-	80.00	cut	2619.60
0004 03-01-0104-2061-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	cut	20% - 2095.68 SN 80.
						SUB-TOTAL	: 2,175.68

JOB NATURE

0000 PB	PANEL BEATING	800.00	525	
0001 SP	SPRAYPAINT CHARGE	1000.00	600	
0002 20-204	REMOVE/REFIX UPHOLSTERY REAR	100.00	60.	
0003 L	TRANSFER DOOR PARTS	120.00	60.	1245
				SUB-TOTAL : 2,020.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2095.68
80
1245
3420.68
03 days