

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305533028
Date 19.10.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : Mr TAUFIKH
Vehicle Reg No. SHB4451A Date of Accident : 13.10.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: **AXA** --- **SKK3189G**
- The finalized amount shall be:
 - Spare Parts after List discount \$2,175.68
 - Labour Charges \$1,245.00
 - Total for Part-By-Part Repair Cost \$3,420.68**
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance. We confirm the estimates and finalized amount

Signature :
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : *taufikh*
Name : TAUFIKH
Date : 15/11/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305533028
 REGN NO : SHB4451A
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 29.01.2021
 DATE/TIME IN : 14.10.2022 13:45
 ACCIDENT DATE : 13.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0595-G	PANEL ASSY-REAR DOOR RH#	1	2,147.90	20.00	1,718.32
0002 04-01-0104-2470-G	MOULDING ASSY-W/LINE RR D	1	125.30	20.00	100.24
0003 28-01-9999-2032-A	ZIG BOOK NOW APP LOGO REA	1 N	80.00	2.00-	80.00
0004 03-01-0104-2137-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12

SUB-TOTAL : 2,175.68

JOB NATURE

0000 PB	PANEL BEAT(SHB4451A)TP	525.00
0001 SP	SPRAYPAINT CHARGE	600.00
0002 20-204	REMOVE/REFIX UPHOLSTERY REAR	60.00
0003 L	TRANSFER DOOR PARTS	60.00

SUB-TOTAL : 1,245.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.10.2022

REPAIR ESTIMATE

Time: 13:42:55

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305533028
REGN NO : SHB4451A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 29.01.2021
DATE/TIME IN : 14.10.2022 13:4
ACCIDENT DATE : 13.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,420.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :