

ASS. REC. BY:

REP:

CS/SMR2010307/Avy3

ASSIGNMENT

SNB4490R

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **SHD 6368J**

Policy No. _____

Claims No. **TAX/10/22/2054/MA**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **58X**

Yr Regn: **2021, August**

Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Alphard** c.c. **2494**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **20098** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **3TNHS3DH 308056056**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/60R17**

R: **225/60R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **06** mm R/Bal. **06** mm

L/Bal. **06** mm L/Bal. **06** mm

D.O.A. **14/10/22** D.O.I. **03/11/22**

Survey held at

Bifrost

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/3/23 **TP SMRT** Lump Sum \$6100 confirmed by email (Red 27,809.38, 82%)

MV:

PV:

Nett:

Date/Time, File Pass to?

☐ : Prel. Report

1) Date/Time, File Return to?

☐ : Final Report

2) **27/3/23-typist**

Days Of Repair: **6**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

Att / Fee:

Site Insp

Inc Insp

Tech Insp

Planned Payment: **TP**

2 months Payment: **LS \$6100**

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	908H

Vehicle Details

Vehicle No.:	SNB4490R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD HYBRID ELEGANCE (AUTO)
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	2AR2705597
Chassis No.:	JTNHS3DH308056056
Maximum Power Output:	145.0 kW (194 bhp)
Open Market Value:	\$60,768.00
Original Registration Date:	24 Aug 2021
First Registration Date:	24 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$81,383.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2031
PARF Rebate Amount:	\$61,037.00

Intended COE Rebate Details

COE Expiry Date:	23 Aug 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$44,800.00
Total Rebate Amount:	\$105,837.00

The information contained herein is correct as at 26 Oct 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/10/2022 16:20 (SGT)
Reported by	Driver
Date of Accident	14/10/2022 08:31 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	GRANGE ROAD / PETERSON ROAD / IRWELL BANK ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB4490R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN PEI LING
NRIC No	S2165908H
Email Address	MPLTAN@RODAMAS.COM.SG
Mobile Phone No	(Phone) +65-97579455
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Alphard
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2500

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7210102817-01

DRIVER

Name of Driver	S AMEEN BIN ABDULLAH BAHASHWAN
NRIC No	S1773683C
Date Of Birth	01/09/1966
Occupation	Outdoor

Date Of Driving Pass	15/02/2011
Driving experience	11 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86684135
Alt. Phone Number	-
Email Address	AMEENBAHASHWAN@GMAIL.COM
Address	BLK 534 BEDOK NORTH ST 3 #02-840
Address complement	-
Postcode	460534
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6368J
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

Describe Circumstance of the Accident

I was driving along Grang Rd at junction of Patheon Rd and Arwell Road Rd turning right on 1st lane with arrow straight and right turn and 2nd lane a taxi on 2nd lane have turn right but go straight and hit my car right. The car is taxi plate number SHD63685.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

BVEDDDH

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

TP SMRT

Vern

Repair Estimate

Vehicle number: SNB4490R

Make & Model: Toyota Alphard

Chassis number: JTNHS3DH308056056

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$	
1	Front bumper	1	\$ 718.90	x
2	Front bumper RH side retainer	1	\$ 104.20	x
3	Front bumper LH side retainer	1	\$ 104.20	x
4	Front bumper RH side chrome moulding	1	\$ 389.00	x
5	Front bumper RH fog lamp	1	\$ 562.00	x
6	Front bumper RH fog lamp bracket	1	\$ 92.40	x
7	Front bumper RH fog lamp cover	1	\$ 254.00	x
8	Front bumper RH fog lamp cover bracket	1	\$ 101.90	x
9	Front bumper parking sensor rubber seal	2	\$ 26.00	x
10	RH headlamp assy	1	\$ 3,798.60	x
11	RH headlamp chrome moulding	1	\$ 112.10	x
12	Front grille	1	\$ 2,564.40	x
13	Front grille emblem	1	\$ 75.00	x
14	Front grille rubber seal	1	\$ 62.00	x
15	Front RH fender	1	\$ 1,148.90	x
16	Front RH fender splash shield	1	\$ 269.70	x
17	Front RH fender glass with rubber seal	1	\$ 235.10	x
18	Front RH fender lower protector	1	\$ 203.10	x
19	Front RH sport rim	1	\$ 2,494.10	x
20	Front RH lower arm	1	\$ 815.50	x
21	Front RH lower arm ball joint	1	\$ 264.70	x
22	Front RH shock absorber	1	\$ 473.20	x
23	Front RH wheel bearing	1	\$ 670.80	x
24	Front RH knuckle arm	1	\$ 734.50	x
25	Front RH tie rod end	1	\$ 204.30	x
26	Front RH drive shaft	1	\$ 1,251.70	x
27	Steering rack and pinion	1	\$ 1,955.10	x
28	RH side mirror housing assy	1	\$ 1,676.80	x
29	RH front door <i>Dented</i>	1	\$ 1,505.60	x
30	RH front door upper moulding rivets	1 set	\$ 60.00	+
31	RH front door vertical garnish (Front) <i>Front</i>	1	\$ 45.60	+
32	RH front door vertical garnish (Rear)	1	\$ 103.40	+
33	RH front door lower protector <i>Dented</i>	1	\$ 812.20	+
34	RH front door outer handle <i>new</i>	1	\$ 354.60	r
35	RH front door frame sticker (no:01) <i>new</i>	1	\$ 55.80	+

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SNB4490R

Make & Model: Toyota Alphard

Chassis number:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	LH sliding door rubber sensor <i>ut</i>	1	\$ 1,006.70

\$ 1,006.70

Parts less 25% \$ 251.68

Total \$ 755.03

No.	Special Nett Items	Qty	Amount S\$

Total: \$ -

No.	Labour and painting	Amount S\$

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 755.03

Special Nett: \$ -

Labour: \$ -

Total Amount: \$ 755.03

Adnan Ly
*07/11/22**585*
Supplementary 513.75