

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22010325/Tvce2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	07-11-2022 INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 5722L	Veh. Ir	nspected	SHD 8810K	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1193042-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	17/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ V220D	c.c		2143	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	WDF44781323611699	Coloui	r	WHITE	
	Odometer	339889	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/65 R16	GT RAI	DIAL	6 mm	
	L/H Front Tyre	205/65 R16	GT RAI		6 mm	
	R/H Rear Tyre	205/65 R16	GT RAI		6 mm	
	L/H Rear Tyre	205/65 R16	GT RAI	DIAL	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/10/2022	Inspec	tion Date	17/10/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					