

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 126k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 88521M Yr Regn: 14/3/19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe c.c. 2359

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading 77257 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMHS381PSK U095904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front

R/Bal. 5 mm

U/Bal. 5 mm

D.O.A. 12/10/22

Survey held at Kamoco

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front LH

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

MV-126K

Steve confirmed final fig :\$5929.84 and 4 days

(red, 2395.60, 29%)

Date/Time, File Pass W7

1) 28/10/22

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / L.B.H. (\$) 5929.84

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$ _____)
☐ Interview (\$ _____)
☐ Tech. Invs (\$ _____)
☐ Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

160

50

50

42

302