

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 9249D

at Workshop m/s HIAP LOK AUTOMOBILE

of 160, SIN MING DR #05-17

Insured: ALS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 81K

IDAC Accident Rport: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR 9249D Yr Regn: 2017 / BKH

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Touran 1.4TSI c.c. 1395

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 66157 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV9 222ITZH 070682

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/10/22 D.O.I. 19/10/22

Survey held at HIAP LOK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 43K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K - 5K) / 6 days

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

2) _____

Transportation: _____

Add Fee: : Site Insp (\$ _____)

____ S + RS ____ SI

: Interview (\$ _____)

Photos

: Tech. Invs (\$ _____)

Others

: Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC
Owner ID: 378C

Vehicle No.: SLR9249D
Vehicle to be Exported: No
Intended Deregistration Date: 20 Oct 2022
Vehicle Make: VOLKSWAGEN
Vehicle Model: TOURAN 1.4 TSI TL 5T12NZ
Primary Colour: White
Manufacturing Year: 2017
Engine No.: CZD279119
Chassis No.: WVGZZZ1TZH070682
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$23,111.00
Original Registration Date: 31 Aug 2017
First Registration Date: 31 Aug 2017
Transfer Count: 1
Actual ARF Paid: \$19,356.00

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Aug 2027
PARF Rebate Amount: \$13,549.00

COE Expiry Date: 30 Aug 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,001.00
COE Rebate Amount: \$24,301.00
Total Rebate Amount: \$37,850.00

The information contained herein is correct as at 20 Oct 2022

OK

Volkswagen Touran 1.4A TSI Comfortline

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$90,980

Depreciation

\$14,000 /yr

[View models with similar depre](#)

Reg Date

30-Apr-2018

(5yrs 6mths 9days COE left)

Mileage

129,960 km (29k /yr)

Manufactured

2018

Road Tax

\$624 /yr

Transmission

Auto

Dereg Value

\$41,033 as of today (change)

OMV

\$25,137

COE

\$37,330

ARF

\$27,192

Engine Cap

1,395 cc

Power

110.0 kW (147 bhp)

Curb Weight

1,288 kg

No. of Owners

1

Type of Vehicle

MPV