

(08/11/22) wef

ASS. REC. BY: ASU

REF:

CS/ASM 220 10366/Rvy 3

850B

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 62194at Workshop m/s TC PK ENTERPRISEof 5033, AMK Ind PK 2 #101267Insured: ASM

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 79K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMN 62194 Yr Regn: 7019 / BuhType M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA JAZZ 1.3 CVT c.c. 1318Colour BLUE A/C: Insured / Std / NI / NASp. Reading 035072 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK 3850K S217982Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/65R15R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 13/10/22Survey held at TC PK

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 12/10/22Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 55KESTIMATE RANGE OF REPAIR / NO. OF days - (3K - 4K) / 7 days

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1) Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / L.R. / \$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	850B
Vehicle No.:	SMN6219U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Oct 2022
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	L13B14101536
Chassis No.:	JHMGK3850K5217982
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$16,213.00
Original Registration Date:	21 Aug 2019
First Registration Date:	21 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$6,213.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2029
PARF Rebate Amount:	\$4,659.00
COE Expiry Date:	20 Aug 2029
COE Category:	A- Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,999.00
COE Rebate Amount:	\$18,449.00
Total Rebate Amount:	\$23,108.00

The information contained herein is correct as at 20 Oct 2022

OK

Honda Jazz 1.3A

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price **\$80,000**

Depreciation ⓘ **\$11,170 /yr**
View models with similar depre

Reg Date **05-Sep-2019**
(6yrs 10mths 15days COE left)

Mileage **51,100 km (16.3k /yr)**

Manufactured ⓘ **2019**

Road Tax ⓘ **\$578 /yr**

Transmission **Auto**

Dereg Value ⓘ **\$26,707 as of today (change)**

OMV ⓘ **\$16,333**

COE ⓘ **\$31,917**

ARF ⓘ **\$6,333**

Engine Cap **1,318 cc**

Power **73.0 kW (97 bhp)**

Curb Weight ⓘ **1,052 kg**

No. of Owners ⓘ **1**